

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007691/UWY3Q2**Date:** 05/10/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009842101
Claimant Vehicle No :	SMU7333D	Insured Vehicle No :	SLK1379B
Date of Loss:	15/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205618/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7333D	Engine No:	3ZRB808290
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600081501
Reg. Date:	02/08/2017 (Man. Year: 2016)	Odometer:	67850 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45Z R20	Rear Tyre Size:	255/45Z R20
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	989.85	0.00	989.85	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	650.00	450.00	40.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,089.85	650.00	1,439.85	68.90
+ GST 7.00/7.00% (S\$)	146.29	45.50	100.79	68.90
Nett Amount (S\$)	2,236.14	695.50	1,540.64	68.90

INSPECTION

Date of Assignment:	12/08/2022		
Date Inspected:	22/09/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts: M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU7333D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	1,229.70 FL	*- FL	
2	1		*FRONT BUMPER SIDE RETAINER O/S	Not Necessary	90.10 FL	*- FL	
					Sub Total (\$\$)	1,319.80	0.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	329.95	0.00
					Total Parts (\$\$)	989.85	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	450.00	250.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	400.00
Gross Labour Cost (\$\$)			1,100.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >