

ASS. REC BY: Touffin

REF: CE4/14.1822007698 / T p93

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated cost: \_\_\_\_\_  
OD / TP / IS / TP RES / OD RES / EVA / INV / MV  
 To Inspect/Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: G6L21874 Yr Regn: 2021 March  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Hiace C.C. 2982  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 45676 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JKFHT02P700 251657  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: NB / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/115  
 R: 195/115  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

N/S		O/S	

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$88K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: Eze Vehicle: IN / OUT

Front Rear  
 R/Bal. 6 mm R/Bal. 0 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 12/8/22  
 Survey held at Efficient Motor  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Rep. Format: \_\_\_\_\_  
 Lump Sum / I.B.A. (%) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____

# EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

VEHICLE NO : GBL2187U

MAKE & MODEL : TOYOTA HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P700251657

DATE : 11 AUG 2022

CLAIM TYPE : TP CLAIM

D.O.A : 05 AUG 2022

TO : ALLIANZ

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER		\$ 481.80	\$ <del>481.80</del> 481.80
2	2	REAR BUMPER RETAINER LH/RH		\$ 49.80	\$ <del>X</del> 99.60
3	2	REAR BUMPER UPPER COVER LH/RH		\$ 99.80	\$ <del>X</del> 199.60
4	2	REAR BUMPER UPPER COVER RETAINER LH/RH		\$ 52.90	\$ <del>X</del> 105.80
5	4	REAR BUMPER CENTER BRACKET		\$ 47.70	\$ <del>?</del> 190.80
6	1	REAR WINDSCREEN GLASS		\$ 1,317.50	\$ <del>bmo</del> 1,317.50
7	1	REAR END PANEL OUTER		\$ 363.70	\$ <del>Ry</del> 363.70
8	1	TAILGATE		\$ 2,293.20	\$ <del>bc</del> 2,293.20
9	1	TAILGATE LOCK		\$ 323.60	\$ <del>?</del> 323.60
10	1	TAILGATE WEATHERSTRIP		\$ 433.30	\$ <del>?</del> 433.30
11	1	TAILGATE GARNISH		\$ 151.20	\$ <del>cut</del> 151.20
12	1	TAILGATE LOGO		\$ 72.20	\$ <del>ner</del> 72.20
13	2	TAIL LAMP LH/RH		\$ 324.40	\$ <del>X</del> 648.80
14	1	THIRD BRAKE LIGHT		\$ 203.90	\$ <del>X</del> 203.90
15	1	REAR WIPER ARM		\$ 90.00	\$ <del>y</del> 90.00
16	1	REAR WIPER MOTOR ASSY		\$ 818.10	\$ <del>X</del> 818.10
17	1	REAR BOOT STEP PLATE		\$ 112.30	\$ <del>?</del> 112.30
				<b>\$ 7,235.40</b>	<b>\$ 7,905.40</b>
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  Acknowledged by Repairer Signature: Date:				<b>TOTAL PRICE</b>	<b>\$ 7,905.40</b>
				<b>LESS 25%</b>	<b>\$ 1,976.35</b>
				<b>SUB TOTAL PRICE</b>	<b>\$ 5,929.05</b>

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIP SET		\$ 50.00	\$ <del>30ner</del> 50.00
2	1	REVERSE SENSOR		\$ 200.00	\$ 200.00
3	1	70KM/H STICKER		\$ 30.00	\$ <del>ny</del> 30.00
4	1	SEALANT		\$ 80.00	\$ <del>ny</del> 80.00
5	1	REAR NO. PLATE		\$ 45.00	\$ <del>X</del> 45.00
6	1	PAN PACIFIC METAL PLATE		\$ 80.00	\$ <del>ny 70</del> 80.00
<b>TOTAL S/NETT</b>				<b>\$ 485.00</b>	<b>\$ 485.00</b>

**Labour Charges**

1	To cut/weld, panel beat & align Rear portion, to remove & replace damaged parts.	\$ 1,200.00	600
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 50.00	30
4	To remove & replace reverse sensor.	\$ 100.00	30
5	To remove & refit spare tyre, interior trims to facilitate the repair.	\$ 100.00	60
6	To putty, spray painting Rear Portions & other affected areas.	\$ 1,000.00	700
7	To transfer tailgate components to new tailgate.	\$ 100.00	60
8	To remove & refit rear windscreen glass.	\$ 150.00	120
9	To do artwork sticker on tailgate.	\$ 350.00	150

Tanj M 97495749  
 WP 12/8/22 @ 5 pm  
 4/5 Resurvey after repair

Tanj M e/Hanston  
 05 days

TOTAL LABOUR

\$ 3,150.00

**Total Cost of Repairs**

**\$ 9,564.05**

(Total parts + Total S/Nett + Total Labour Cost)