4/26/23, 3:25 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22007699/EPA3Q2

26/04/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0004983_02

Claimant Vehicle SDN8663M Insured Vehicle No: PC6489D No:

Date of Loss: 01/08/2022 Nature of Claim: TP Claim No: MCV2022D0004208

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDN8663M**

TOYOTA SIENTA, 1.5 STANDARD (A) 2NRX696909 Make & Model: Engine No:

Reg. Date: 21/06/2021 (Man. Year: 2021) Chassis No: MHFZ28H3900071474

Colour: Odometer: 13243 km Silver

Engine Capacity: 1496 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

185/60 R14 185/60 R14 Front Tyre Size: Rear Tyre Size: Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,154.00	1,846.50	8,307.50	81.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,432.00	1,030.00	3,402.00	76.76
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	14,586.00	2,876.50	11,709.50	80.28
	+ GST 8.00/8.00% (S\$)	1,166.88	230.12	936.76	80.28
	Nett Amount (S\$)	15,752.88	3,106.62	12,646.26	80.28
	+ Loss of Use (4.0 x	S\$50.00/day) (S\$)	200.00		
		Nett Liability (S\$)	3,306.62		

INSPECTION

Date of Assignment: 11/08/2022

Premium Automobiles Pte Ltd (HQ) Date Inspected: 11/08/2022 Inspected At:

55 UBI ROAD 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: **CHEN TSUE YEE CHEW HSIAO TONG** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/26/23, 3:25 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Apr 2023)

Parts: M1-MPV TOYOTA SIENTA 1.5 STANDARD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDN8663M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,925.00 FS	*- FS
2	2		*REAR BUMPER SIDE RETAINER -LH/RH	Not Necessary	250.00 FS	*- FS
3	2		*REAR BUMPER SIDE SUPPORT -LH/RH	Not Necessary	250.00 FS	*- FS
4	1		*REAR BUMPER EXTENSION -CENTER	Cut	370.00 FS	*277.50 FS
5	2		*REAR BUMPER EXTENSION -LH/RH	Not Necessary	275.00 FS	*- FS
6	2		*REAR BUMPER REFLECTOR -LH/RH	Not Necessary	219.00 FS	*- FS
7	1		*REAR BUMPER FOGLAMP	Not Necessary	386.00 FS	*- FS
8	1		*REAR LID	Dented	1,479.00 FS	*1,109.25 FS
9	1		*REAR LID WEATHERSTRIP	Not Necessary	495.00 FS	*- FS
10	1		*REAR LID LOGO	Necessary	89.00 FS	*66.75 FS
11	1		*REAR LID EMBLEM SIENTA	Necessary	89.00 FS	*66.75 FS
12	1		*REAR LID EMBLE G	Necessary	60.00 FS	*45.00 FS
13	1		*REAR LID LOCK ASSY	Not Necessary	659.00 FS	*- FS
14	1		*REAR LID STRIKER ASSY	Not Necessary	49.00 FS	*- FS
15	1		*REAR LID CHROME PROTECTOR	Cut	375.00 FS	*281.25 FS
16	1		*REAR LID TOP LAMP	Not Necessary	497.00 FS	*- FS
17	2		*REAR LID LAMP -LH/RH	Not Necessary	396.00 FS	*- FS
18	1		*REAR WIPER ARM	Not Necessary	127.00 FS	*- FS
19	1		*REAR WIPER MOTOR	Not Necessary	927.00 FS	*- FS
20	1		*REAR WIPER	Not Necessary	65.00 FS	*- FS
21	2		*TAIL LAMP -LH/RH	Not Necessary	496.00 FS	*- FS
22	2		*CAR PLATE LIGHT -LH/RH	Not Necessary	126.00 FS	*- FS
23	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*-FS
24	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	ett.	-		
				Total Parts (S\$)	10,154.00	1,846.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	0.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	80.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	120.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	80.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID RE- ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	350.00
7	TO RESPRAY REAR BUMPER AND REAR LID	New	1,200.00	350.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	50.00
	Gross Labou	r Cost (S\$)	4,432.00	1,030.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >