1/4/23, 1:21 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22007702/UPA3Q2

04/01/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492028 **Claimant Vehicle** 

**GBL7072J** Insured Vehicle No: SLJ1637L No:

Date of Loss: 31/07/2022 Nature of Claim: TP Claim No: 9441825278SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBL7072J** 

Make & Model: NISSAN NV350 CARAVAN, 2.0 DX (A) QR20022308R Engine No: Reg. Date: 04/02/2022 (Man. Year: 2021) Chassis No: VR2E26138174 Colour: Odometer: 18266 km Black

**Engine Capacity:** 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

195/80 R15 Front Tyre Size: 195/80 R15 Rear Tyre Size: Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,336.83	1,051.02	3,285.81	75.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,260.00	870.00	40.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,466.83	2,311.02	4,155.81	64.26
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	6,466.83	1,800.00	4,666.83	72.17
+ GST 7.00/7.00% (S\$)	452.68	126.00	326.68	72.17
Nett Amount (S\$)	6,919.51	1,926.00	4,993.51	72.17
+ Loss of Use (4.0 x \$	S\$80.00/day) (S\$)	320.00		
1	Nett Liability (S\$)	2,246.00		

**INSPECTION** 

Date of Assignment: 12/10/2022

Jin Auto Services Pte Ltd (Defu) Date Inspected: 12/10/2022 Inspected At: Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: **CHEW HSIAO TONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	720.60 FL	*720.60 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	88.00 FL	*30.00 FL
3	1		*REAR LH TAIL LAMP	Cracked	242.80 FL	*242.80 FL
4	1		*REAR LH FENDER	Repair	2,162.20 FL	*- FL
5	1		*REAR LH RIM CAP	Cut	174.40 FL	*174.40 FL
6	1		*REAR LH SLIDING DOOR	Repair	1,430.70 FL	*- FL
7 F=Fra	1 inchise	part. S=SpcNe	*REAR LH FENDER STICKER (NPA)  stt. L=ListItemDisc.	Not Necessary	0.00 FS	*-FS
				Sub Total (S\$)	4,818.70	1,167.80
			- List Item Discount o	n L Items 10.00/10.00% (S\$)	481.87	116.78
				Total Parts (S\$)	4,336.83	1,051.02
			Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR CHARGE	New	980.00	600.00
2	SPRAY PAINTING	New	880.00	600.00
3	TUFF COAT	New	80.00	0.00
4	WIRING	New	30.00	20.00
5	LABOUR CHARGE FOR R&R REAR REVERSE SENSOR	New	80.00	40.00
6	CONDUCT WHEEL ALIGNMENT	New	80.00	0.00
		Gross Labour Cost (S\$)	2,130.00	1,260.00
	Report was unsubmit	ted during this print-out.		

< END OF ESTIMATES >