

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22007707/APA3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220027407
Claimant Vehicle No :	EU8838C	Insured Vehicle No :	SGQ198R
Date of Loss:	01/08/2022	Nature of Claim:	TP
		Claim No:	8579261114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EU8838C	Engine No:	CHZ362117
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V1H1071888
Reg. Date:	29/05/2017 (Man. Year: 2017)	Odometer:	77089 km
Colour:	Silver		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,895.00	0.00	13,895.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,242.00	1,610.00	56.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,747.00	1,242.00	15,505.00	92.58
+ GST 8.00/8.00% (S\$)	1,339.76	99.36	1,240.40	92.58
Nett Amount (S\$)	18,086.76	1,341.36	16,745.40	92.58
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,643.36		

INSPECTION

Date of Assignment:	15/08/2022		
Date Inspected:	15/08/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,432.00 FS	*- FS
2	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	43.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	179.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	571.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LH	Not Necessary	318.00 FS	*- FS
6	1		*FRONT BUMPER STRIP MOLDING TRIM -LH	Not Necessary	182.00 FS	*- FS
7	1		*FRONT BUMPER WHEEL HOUSING LINER ADAPTER -LH	Not Necessary	42.00 FS	*- FS
8	1		*RADIATOR GRILLE	Not Necessary	1,578.00 FS	*- FS
9	1		*RADIATOR GRILLE END PANEL	Not Necessary	210.00 FS	*- FS
10	1		*RADIATOR AIR GUIDE GRILLE -LH	Not Necessary	210.00 FS	*- FS
11	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
12	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	136.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
16	1		*FRONT HIGH TONE SIGNAL HORN RETAINER -LH	Not Necessary	213.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	183.00 FS	*- FS
18	1		*HEADLIGHT -LH	Not Necessary	5,879.00 FS	*- FS
19	1		*LIFT CYLINDER	Not Necessary	156.00 FS	*- FS
20	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
21	1		*RADIATOR AIR GUIDE -LH	Not Necessary	28.00 FS	*- FS
22	1		*RADIATOR AIR GUIDE -UPPER CENTRE	Not Necessary	14.00 FS	*- FS
23	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
24	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

13,895.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFE FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,852.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >