

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22007714/KYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000127
Claimant Vehicle No :	SHC5323A	Insured Vehicle No :	SNG1617L
Date of Loss:	10/08/2022	Nature of Claim:	TP
		Claim No:	1779356446SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5323A		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H94800
Reg. Date:	25/02/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU003093762
Colour:	Metallic Pearl White/Red	Odometer:	108971 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 7 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Wanli 7 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,061.65	705.07	2,356.58	76.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,540.00	470.00	8,070.00	94.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,601.65	1,175.07	10,426.58	89.87
+ GST 7.00/7.00% (S\$)	812.12	82.25	729.87	89.87
Nett Amount (S\$)	12,413.77	1,257.32	11,156.45	89.87
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$96.30/day) (S\$)		288.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,703.67		

INSPECTION

Date of Assignment:	11/08/2022		
Date Inspected:	11/08/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*COVER ,REAR BUMPER LOWER	Serviceable	22.00 FL	*- FL
4	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	374.50 FL	*374.50 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
6	1		*REFLECTOR ASSY ,REFLEX ,LH	Serviceable	39.00 FL	*- FL
7	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
8	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
9	1		*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
11	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
12	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
13	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
14	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
15	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,707.20	920.10
- List Item Discount on L Items 25.00/25.00% (\$)	645.55	215.03
Total Parts (\$)	3,061.65	705.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
10	TOWING FEES	New	150.00	0.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	220.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
14	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TESTG) TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
15	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
16	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (S\$)			8,540.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >