



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1381T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	1,355.00	586.18
1	FRONT RH FOG LAMP	CUT	335.00	290.00
1	FRONT BUMPER BOTTOM GARNISH	DEFORMED	165.00	165.00
1	FRONT BUMPER BRACKET	DEFORMED	95.00	95.00
1	FRONT BUMPER TOP COVER	NOT NECESSARY	165.00	-
1	FRONT RH HEAD LAMP	CRACKED	2,219.00	2,219.00
1	WATER TANK	DEFORMED	569.00	195.60
1	FRONT RH HEAD LAMP RETAINER	NOT NECESSARY	166.00	-
1	FRONT RH FENDER	BENT	789.00	789.00
1	FRONT RH RIM	TO REPAIR SEE LABOUR	1,250.00	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,165.00	-
1	FRONT BONNET RH HINGE	TO REPAIR SEE LABOUR	168.00	-
1	FRONT BONNET LH HINGE	TO REPAIR SEE LABOUR	168.00	-
1	FRONT RH SIDE MUD FLAP	TORN	226.00	150.00
1	FRONT RH WHEEL ARC FLAP	DEFORMED	289.00	198.50
	LESS 25% DISCOUNT		-2,281.00	-1,172.07
			6,843.00	3,516.21
	<u>LABOUR</u>			
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT RIGHT PORTIONS; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF FRONT RH RIM, FRONT BONNET, FRONT BONNET RH HINGE AND FRONT BONNET LH HINGE.		800.00	600.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS. (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING. (NPA)	NOT NECESSARY	-	-
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT. (NPA)	NOT NECESSARY	-	-
	SPRAY PAINTING FOR FRONT PORTIONS AFFECTED PARTS.		1,000.00	700.00

Report Ref No. CS/INC22007720/Tny3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REFOCUSING OF THE FRONT HEADLAMP.		180.00	40.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE.	NOT NECESSARY	120.00	-
	3D WHEEL ALIGNMENT.		180.00	80.00
	TO APPLY WATERPROOFING SEALER ON END PANELS. (NPA)	NOT NECESSARY	-	-
			2,280.00	1,420.00
GRAND TOTAL			9,123.00	4,936.21
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,900.00

Report Ref No. CS/INC22007720/Tny3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.