

A.C.S. REC BY: TaujuaREF: CS/INC 22067720/Tny3

ASSIGNMENT

From: _____ Date: _____

Estimated lost: _____

OD (TP) / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 970K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK1381T Yr Regn: 2017 JanType: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hybrid C.C. 1797Colour: White A/C: Insured / Std / Nil / NASp. Reading: 269744 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 8T0K133EU 603542529Gen. Cond: (G) Good / Fair / Poor / BurntSteering: (I) In order / Jammed / Leaked / Burnt orBrake: (I) In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Windleforce

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 15/07/22 0530pm

Survey held at

Auto Mega

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

Date/Time, File Pass to?

☐ : Prel. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Report Format: _____

Lump Sum / I.B.L. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLK1381T
Chassis No: JTDKB3FU603542524
Engine No: 2ZRR986309

Report No : AMM2208-08
Date : 12.08.2022

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged	\$ 1,355.00	\$ 1,219.50 <i>mu</i>
2	1	Front RH Fog Lamp	Broken	\$ 335.00	\$ 301.50 <i>cut</i>
3	1	Front Bumper Bottom Garnish	Damaged	\$ 165.00	\$ 148.50 <i>de</i>
4	1	Front Bumper Bracket	Necessary	\$ 95.00	\$ 85.50 <i>de</i>
5	1	Front Bumper Top Cover	Necessary	\$ 165.00	\$ 148.50 <i>X</i>
6	1	Front RH Head Lamp	Damaged	\$ 2,219.00	\$ 1,997.10 <i>Cna</i>
7	1	Water Tank	Damaged	\$ 569.00	\$ 512.10 <i>de</i>
8	1	Front RH Head Lamp Retainer	Damaged	\$ 166.00	\$ 149.40 <i>X</i>
9	1	Front RH Fender	Dented	\$ 789.00	\$ 710.10 <i>bt</i>
10	1	Front RH Rim	Scratch	\$ 1,250.00	\$ 1,125.00 <i>Rp</i>
11	1	Front Bonnet	Impacted	\$ 1,165.00	\$ 1,048.50 <i>Rp</i>
12	1	Front Bonnet RH Hinge	Impacted	\$ 168.00	\$ 151.20 <i>Rp</i>
13	1	Front Bonnet LH Hinge	Impacted	\$ 168.00	\$ 151.20 <i>Rp</i>
14	1	Front RH Side Mud Flap	Damaged	\$ 226.00	\$ 203.40 <i>tu</i>
15	1	Front RH Wheel Arc Flap	Damaged	\$ 289.00	\$ 260.10 <i>de</i>
				\$11,405.00	\$ 10,264.50

Total (Parts): \$11,405.00 -25% \$ 10,264.50

Labour Charges

26	To fix & dismantle and remove damaged Front Right Portions; affected damaged portion.	\$ 800.00	600
27	To apply anti rust coat and affected areas	\$ -	
28	To check wiring	\$ -	
29	Welding and cutting of affected panels, including chassis alignment.	\$ -	
30	Spray painting for Front Portions affected parts	\$ 1,000.00	700
31	Refocusing of the front headlamp	\$ 180.00	40
32	Diagnose ECU system and reset error code.	\$ 120.00	X
33	3D Wheel Alignment	\$ 180.00	80
34	To Apply Waterproofing sealer on End Panels	\$ -	

Total Labour: \$ 2,280.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$12,544.50

Less 20% \$10,035.60

AMM PTE LTD

Tanjiu 97445749
wp 15/8/22 @ 5:50pm
1/5 Resurvey after repair
tanjiu@lkhauto.com
04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: