

ASIS REC BY: T. J. J. J.

REF: 03/INC 22007771/Try 3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBK 5234C**

Policy No. _____

Claims No. **MT/1183720-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	☒

Bal. or Market Value: 885K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS UP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBK 64796 Yr Regn: 2020, Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2759

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 59188 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDM2012014006*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/15

R: 15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Rota 119

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 9/8/2022 D.O.I. 15/8/22 0515pm

Survey held at Auto mega

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
18/4/23	Lump Sum \$6250 confirmed by email (red 6560.09, 51%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 18/4/23-typist

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: TP

Lump Sum / L.B. / LS \$6250

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: GBK6479G
Chassis No: GDH2012014006
Engine No: IGD8606100

Report No : AMM2208-06
Date : 15.08.2022

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Bumper	Necessary	\$ 758.00	\$ 682.20
2	2	Rear Bumper Sensor	Necessary	\$ 516.00	\$ 464.40
3	1	Rear RH Side Panel	Necessary	\$ 1,670.00	\$ 1,503.00
4	1	RH Tail Lamp	Necessary	\$ 475.00	\$ 427.50
5	1	Rear RH Tail Lamp Side Inner Panel	Necessary	\$ 575.00	\$ 517.50
6	1	Rear RH Bumper Side Inner Panel	Necessary	\$ 365.00	\$ 328.50
7	1	Rear End Step Panel	Damaged	\$ 585.00	\$ 526.50
8	1	Rear Boot	Necessary	\$ 2,162.70	\$ 1,946.43
9	1	Rear Boot Moulding	Necessary	\$ 536.00	\$ 482.40
10	1	Rear End Panel	Damaged	\$ 525.00	\$ 472.50
11	1	Rear Boot Lock	Damaged	\$ 468.00	\$ 421.20
12	1	Rear Boot Catch	Damaged	\$ 88.00	\$ 79.20
13	1	Rear Air Vent Cover	Necessary	\$ 95.00	\$ 85.50
14	1	Rear RH Bumper Bracket	Necessary	\$ 82.70	\$ 74.43
15	1	Exhaust Box	Dented	\$ 687.00	\$ 618.30
16	1	Rear Boot Cover	Damaged	\$ 288.00	\$ 259.20
17	1	Rear Windscreen	Necessary	\$ 1,455.00	\$ 1,309.50
18	1	Rear Windscreen Moulding	Necessary	\$ 286.00	\$ 257.40
				\$10,455.66	\$ 9,410.09

Total (Parts): \$ 10,455.66 -25% \$ 9,410.09

Labour Charges

26	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ 1,000.00	600
27	To apply anti rust coat and affected areas	\$ 120.00	50
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00	400
30	Spray painting for Rear Portions affected parts	\$ 1,000.00	800
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ -	
33	3D Wheel Alignment	\$ 120.00	X
34	To Apply Waterproofing sealer on End Panels	\$ 180.00	40

Total Labour: \$ 3,400.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$12,810.09

Less 20% \$10,248.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfimin 97495749
WP 15/8/2022 515 pm
413 Reply after repair
tanfimin@lkkauto.com
Bday