



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: DAVID PHUA

Ref: CS/INC22007721/Tvy3m4

Date: 20/04/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 5234C	Veh. Inspected	GBK 6479G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1183720-002	Excess (\$)	0.00
Assign From	DIANA TAY	Assign Date	15/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GDH2012014006	Colour	SILVER
Odometer	59188 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/R15	ROTALLA	6 mm
L/H Front Tyre	195/R15	ROTALLA	6 mm
R/H Rear Tyre	195/R15	ROTALLA	6 mm
L/H Rear Tyre	195/R15	ROTALLA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/08/2022	Inspect Date / Time	15/08/2022 (05:15 PM)
Survey held at	8 KAKI BUKIT AVE 4 #02-13 PREMIER @ KAKI BUKIT		
Repairer	AUTO MEGA MALL PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**