

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22007724/ECY3M4**Date:** 05/04/2023**REFERENCE**

Insured/Claimant:	SL7 EATING HOUSE	Policy No:	DMCG22003532	
Date of Loss:	02/08/2022	Nature of Claim:	OD	Claim No: CDMCG22001568

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6692H		Engine No:	6HK1696274
Make & Model:	ISUZU FSR34SUQCC, 7.8 D (M)		Chassis No:	JALFSR347H7000017
Reg. Date:	28/06/2017 (Man. Year: 2017)		Odometer:	118873 km
Colour:	White			
Engine Capacity:	7790 cc			
Market Value/New Car Price:	S\$88,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/70R19.5	Rear Tyre Size:	265/70R19.5
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,333.40	8,298.40	2,035.00	19.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,930.00	520.00	15.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,783.40	11,228.40	2,555.00	18.54
Approved Total (Overridden) (\$\$)		9,000.00		
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	13,783.40	8,250.00	5,533.40	40.15
+ GST 7.00/8.00% (\$\$)	964.84	660.00	304.84	31.59
Nett Amount (\$\$)	14,748.24	8,910.00	5,838.24	39.59

INSPECTION

Date of Assignment:	15/08/2022 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
Date Inspected:	15/08/2022 Inspected At:	BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Apr 2023)	
Parts:	N/A	ISUZU FSR34SUQCC 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6692H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE (WCP)	Broken	25.00 F	*25.00 F
2	1		*FRT BUMPER (WCP)	Dented	780.00 F	*780.00 F
3	2		*FRT BUMPER LOWER CTR SIDE GARNISH LH/RH (WCP)	Crushed	50.00 F	*50.00 F
4	2		*FRT BUMPER UPPER STEP GARNISH (WCP)	Necessary	56.00 F	*56.00 F
5	2		*FRT BUMPER BRACKET (WCP)	Bent	110.00 F	*110.00 F
6	1		*FRT GRILLE (WCP)	Broken	485.00 F	*485.00 F
7	2		*FRT GRILLE LOWER APRON (WCP)	Not Necessary	20.00 F	*- F
8	10		*FRT GRILLE CLIPS(+) (WCP)	Necessary	50.00 F	*15.00 F
9	10		*FRT GRILLE CLIPS(-) (WCP)	Necessary	50.00 F	*15.00 F
10	1		*FRT PANEL (WCP)	Dented	1,100.00 F	*1,100.00 F
11	2		*FRT PANEL HINGE (WCP)	Not Necessary	180.00 F	*- F
12	2		*FRT PANEL LOCK (WCP)	Not Necessary	100.00 F	*- F
13	1		*FRT PANEL ISUZU LOGO (WCP)	Necessary	120.00 F	*120.00 F
14	2		*FRT HEADLAMP (WCP)	Broken	520.00 F	*520.00 F
15	2		*FRT SIGNAL LAMP (WCP)	Broken	160.00 F	*160.00 F
16	2		*FRT CORNER PANEL (WCP)	Broken	380.00 F	*380.00 F
17	2		*FRT CORNER PANEL SEAL (WCP)	Necessary	40.00 F	*40.00 F
18	1		*FRT WIPER PANEL (WCP)	Dented	185.00 F	*185.00 F
19	2		*FRT WIPER ARM (WCP)	Bent	210.00 F	*210.00 F
20	2		*FRT WIPER BLADE (WCP)	Crushed	70.00 F	*70.00 F
21	2		*FRT STEP GARNISH (WCP)	Broken	290.00 F	*290.00 F
22	1		*FRT WINDSCREEN (WCP)	Necessary	1,500.00 F	*1,500.00 F
23	1		*FRT WINDSCREEN TOP MOULDING (WCP)	Necessary	100.00 F	*100.00 F
24	1		*FRT WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
25	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
26	1		*FRT WINDSCREEN LOWER MOULDING (WCP)	Necessary	120.00 F	*120.00 F
27	1		*FRT CHASSIS CROSSMEMBER (WCP)	Not Necessary	650.00 F	*- F
28	2		*FRT CHASSIS CROSSMEMBER BRACKET (WCP)	Not Necessary	700.00 F	*- F

Supplementary #1

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*AIRCON BLOWER ASSY (WCP)	Broken	850.00 F	*850.00 F
30	8		*FRT PANEL SIDE CLIP (WCP)	Necessary	24.00 F	*24.00 F
31	8		*FRT CORNER PANEL CLIP (SQUARE) (WCP)	Necessary	24.00 F	*24.00 F
32	1		*FRT PANEL TOP SEAL (WCP)	Torn	75.00 F	*75.00 F
33	2		*FRT BUMPER BRACKET (WCP)	Not Necessary	130.00 F	*- F
34	1		*BRAKE MASTER PUMP BASE HOLDER (WCP)	Broken	180.00 F	*180.00 F
F=Franchise part. S=SpcNett.						
					Sub Total (\$\$)	9,400.00 7,550.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	933.40 748.40
					Total Parts (\$\$)	10,333.40 8,298.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, WELD,REMOVE & FIX ABOVE PARTS	New	1,600.00	1,400.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	1,200.00	1,000.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO DIAGNOSE & RESET FAULT CODE	New	100.00	50.00
5	TO REMOVE & REFIX FRT WINDSCREEN	New	150.00	150.00
6	TO REMOVE & REFIX FRT DASHBOARD	New	250.00	200.00
7	TOP UP AIRCON GAS	New	100.00	100.00
Gross Labour Cost (S\$)			3,450.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >