

Vehicle Damage Assessment Report for [YP6692H]

Estimate Created: 24/03/2023 13:10 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 24/03/2023 13:29 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Isuzu	Model	D-Max
Engine Type	1KDFTV		
License Plate Number	YP6692H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Vehicle Make and Model: ISUZU FSR34P	Insurlogic 4 (24/03/2023 13:29)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$9,000.00 WITH 12 WORKING DAYS	Insurlogic 4 (24/03/2023 13:29)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front number plate		1	25.00	10.00 %	27.50
Front bumper		1	780.00	10.00 %	858.00
Front bumper lower center side garnish LH/RH		2	25.00	10.00 %	55.00
Front bumper upper step garnish		2	28.00	10.00 %	61.60
Front bumper bracket		2	55.00	10.00 %	121.00
Front grille		1	485.00	10.00 %	533.50
Front grille clips (+)		1	15.00	10.00 %	16.50
Front grille clips (-)		1	15.00	10.00 %	16.50
Front panel		1	1100.00	10.00 %	1,210.00
Front panel Isuzu logo		1	120.00	10.00 %	132.00
Headlamp		2	260.00	10.00 %	572.00
Front signal lamp		2	80.00	10.00 %	176.00
Front corner panel		2	190.00	10.00 %	418.00
Front corner panel seal		2	20.00	10.00 %	44.00
Front wiper panel		1	185.00	10.00 %	203.50
Front wiper arm		2	105.00	10.00 %	231.00
Front wiper blade		2	35.00	10.00 %	77.00
Front step garnish		2	145.00	10.00 %	319.00
Front windscreen		1	1500.00	10.00 %	1,650.00
Front windscreen top moulding		1	100.00	10.00 %	110.00
Front windscreen lower moulding		1	120.00	10.00 %	132.00
Aircon blower assy		1	850.00	10.00 %	935.00
Front panel side clips		8	3.00	10.00 %	26.40
Front corner panel clips		8	3.00	10.00 %	26.40
Front panel top seal		1	75.00	10.00 %	82.50
Brake master pump base holder		1	180.00	10.00 %	198.00

Parts Subtotal 8,232.40

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
ERP bracket		1.0	26.00	0.00 %	26.00
Front windscreen sealant		1.0	40.00	0.00 %	40.00

Materials Subtotal 66.00

LaborReplace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel Beating	RnR	1400.00	0.00 %	1,400.00
Checking wiring	RnR	30.00	0.00 %	30.00
To diagnose and reset fault code	RnR	50.00	0.00 %	50.00
To remove and refix front windscreen	RnR	150.00	0.00 %	150.00
To remove & refix front dashboard	RnR	200.00	0.00 %	200.00
Top up aircon gas	RnR	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	1000.00	0.00 %	1,000.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,930.00

Paint Labor Subtotal 1,000.00

Labor Subtotal 2,930.00

Summary

Repair Cost 11,228.40

Discount(20 %) (2,245.68)

8,982.72

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 8,982.72