

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007726/UQY3Q2**Date:** 14/10/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00108152104

**Claimant Vehicle
No :** GBH8867Y**Insured Vehicle
No :** GBC7948E

Date of Loss: 28/07/2022

Nature of Claim: TP

Claim
No: SNM22D205620/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH8867Y**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M)

Engine No: 1KD2828678

Reg. Date: 17/10/2018 (Man. Year: 2018)

Chassis No: JTFHT02P100245661

Colour: White

Odometer: 130937 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,911.00	1,400.00	9,511.00	87.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	980.00	3,090.00	75.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,981.00	2,380.00	12,601.00	84.11
Approved Total (Overridden) (\$\$)		1,900.00		
(\$\$)	14,981.00	1,900.00	13,081.00	87.32
+ GST 7.00/7.00% (\$\$)	1,048.67	133.00	915.67	87.32
Nett Amount (\$\$)	16,029.67	2,033.00	13,996.67	87.32

INSPECTION

Date of Assignment: 15/08/2022

Date Inspected: 14/09/2022 Inspected At:

Carsmith Private Limited (HQ)
13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ
CENTRE
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH8867Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BODY PANEL RH	Repair	2,822.00 FL	*- FL
2	1		*REAR BODY ROLLER GARNISH RH	Not Necessary	511.00 FL	*- FL
3	1		*REAR TAILLAMP RH	Cracked	391.00 FL	*361.00 FL
4	1		*REAR TAILLAMP PANEL RH	Repair	422.00 FL	*- FL
5	1		*REAR TAILGATE	Not Necessary	2,590.00 FL	*- FL
6	1		*REAR TAILGATE ABSORBER RH	Not Necessary	355.00 FL	*- FL
7	1		*REAR TAILGATE ABSORBER LH	Not Necessary	355.00 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	374.00 FL	*- FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	65.00 FL	*- FL
10	1		*TAILGATE INNER TRIM	Not Necessary	183.00 FL	*- FL
11	1		*TAILGATE EMBLEM	Not Necessary	76.00 FL	*- FL
12	1		*REAR BUMPER	Deformed / Torn	593.00 FL	*593.00 FL
13	1		*REAR BUMPER RETAINER RH	Cracked	55.00 FL	*55.00 FL
14	1		*REAR BUMPER RETAINER LH	Not Necessary	55.00 FL	*- FL
15	1		*REAR CORNER PANEL RH	Torn	381.00 FL	*151.00 FL
16	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	191.00 FL	*- FL
17	1		*REAR BUMPER INNER BRACKET	Not Necessary	360.00 FL	*- FL
18	1		*END PANEL -INNER	Not Necessary	890.00 FL	*- FL
19	1		*END PANEL -OUTER	Repair	388.00 FL	*- FL
20	1		*END PANEL UPPER TRIM	Not Necessary	299.00 FL	*- FL
21	1		*REAR EXHAUST	Not Necessary	584.00 FL	*- FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	60.00 FL	*- FL
23	1		*REAR SPARE TYRE BRACKET	Not Necessary	308.00 FL	*- FL
24	1		*SET REAR TAILGATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET REAR REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
27	1		*70KM/H STICKER	Not Necessary	80.00 FS	*- FS
28	1		*JOINT SELAANT	Not Necessary	150.00 FS	*- FS
29	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
30	1		*COMPANY STICKER		800.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,988.00	1,690.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,077.00	290.00
Total Parts (\$\$)	10,911.00	1,400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	20.00
2	REMOVE ,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	0.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	40.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	0.00
7	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,500.00	500.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	420.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			4,070.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >