

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007729/ACY3Q2**Date:** 03/11/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00004622203		
Claimant Vehicle No :	GBB914D	Insured Vehicle No :	PC7922M		
Date of Loss:	12/08/2022	Nature of Claim:	TP	Claim No:	SNM22D205643/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB914D		Engine No:	ZD30170589K
Make & Model:	NISSAN CABSTAR, 2.0 (M)		Chassis No:	JN1SC2F24Z0800295
Reg. Date:	17/07/2008 (Man. Year: 2008)		Odometer:	0 km
Colour:	Gold			
Engine Capacity:	2953 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	Triangle 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,020.38	6,355.82	11,664.56	64.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	2,880.00	1,100.00	27.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,000.38	9,235.82	12,764.56	58.02
Approved Total (Overridden) (\$\$)		7,000.00		
(\$\$)	22,000.38	7,000.00	15,000.38	68.18
+ GST 7.00/7.00% (\$\$)	1,540.03	490.00	1,050.03	68.18
Nett Amount (\$\$)	23,540.41	7,490.00	16,050.41	68.18

INSPECTION

Date of Assignment:	15/08/2022	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	15/08/2022 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Nov 2022)	
Parts:	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB914D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL BOARD	Distorted	1,688.10 FL	*1,388.00 FL
2	1		*TAIL LAMP	Cracked	272.00 FL	*272.00 FL
3	1		*TAIL LAMP BRACKET	Bent	128.10 FL	*128.10 FL
4	1		*REAR END MEMBER	Repair	1,086.25 FL	*- FL
5	4		*TAIL BAORD HINGE	Not Necessary	291.60 FL	*- FL
6	1		*TAIL BAORD SIDE LOCK	Damaged	226.90 FL	*226.90 FL
7	1		*TAIL BAORD SIDE LOCK CATCH	Not Necessary	90.30 FL	*- FL
8	2		*TAIL BOARD RUBBER STOPPER	Missing	136.40 FL	*45.00 FL
9	1		*TAIL BOARD RUBBER STOPPER BRACKET	Bent	103.20 FL	*103.20 FL
10	1		*SIDE GATE O/S	Repair	2,018.00 FL	*- FL
11	1		*FRONT BUMPER	Deformed	1,091.20 FL	*698.00 FL
12	1		*FRONT BUMPER BRACKET	Not Necessary	394.00 FL	*- FL
13	1		*FRONT BUMPER BEAM	Bent	682.00 FL	*521.00 FL
14	1		*FRONT GRILLE	Cracked	903.10 FL	*438.00 FL
15	4		*FRONT GRILLE CLIP	Necessary	19.40 FL	*19.40 FL
16	1		*FRONT GRILLE LOGO	Necessary	116.20 FL	*116.20 FL
17	1		*HEADLAMP	N/S Smashed	2,547.80 FL	*518.00 FL
18	1		*FRONT PANEL	Repair	1,672.00 FL	*- FL
19	1		*FRONT PANEL BADGE -CABSTAR	Necessary	102.00 FL	*102.00 FL
20	1		*FRONT CORNER PANEL	Buckled	563.10 FL	*390.00 FL
21	1		*FRONT WIPER PANEL	Not Necessary	719.60 FL	*- FL
22	1		*FRONT WIPER ARM	Not Necessary	483.10 FL	*- FL
23	1		*SIDE MIRROR BRACKET	Not Necessary	482.00 FL	*- FL
24	1		*SIDE MIRROR-SQUARE	Not Necessary	164.10 FL	*- FL
25	1		*SIDE MIRROR-ROUND	Not Necessary	103.00 FL	*- FL
26	1		*FRONT DOOR -LH	Buckled	1,893.00 FL	*1,474.00 FL
27	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	373.20 FL	*- FL
28	1		*FRONT DOOR INNER BOARD	Not Necessary	722.00 FL	*- FL
29	10		*FRONT DOOR INNER BOARD CLIP	Not Necessary	51.00 FL	*- FL
30	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*30.00 FS
31	1		*REAR NUMBER PLATE	Bent	40.00 FS	*30.00 FS
32	1		*REAR PARKING SENSOR	Damaged	260.00 FS	*200.00 FS
33	1		*TAIL BOARD STICKER -70KM/H	Necessary	20.00 FS	*10.00 FS
34	1		*TAIL BOARD STICKER -13 PAX	Necessary	20.00 FS	*10.00 FS
35	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*REAR STEP PANEL	Bent	350.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,932.65	6,999.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,912.27	643.98
Total Parts (\$\$)	18,020.38	6,355.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE -FRONT	New	1,100.00	600.00
2	LABOUR CHARGE -REAR	New	900.00	900.00
3	SPRAY PAINTING -FRONT	New	850.00	600.00
4	SPRAY PAINTING -REAR	New	750.00	600.00
5	TO REMOVE & INSTALL FRONT WINDSCREEN	New	150.00	0.00
6	CARRY OUT ANTI RUST TREATMENT	New	150.00	120.00
7	CHECK WIRING FOR PROPER FUNCTIONS	New	80.00	60.00
Gross Labour Cost (\$\$)			3,980.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >