

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22007733/UCY3M4**Date:** 04/10/2022**REFERENCE**

Insured/Claimant: CCA LEASING PTE. LTD. Policy No: DMHCSNA00008572100

Date of Loss: 10/08/2022

Nature of Claim: OD

Claim No: SNM22D205653/C01/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMQ3674S**

Make &amp; Model: HONDA FIT, 1.5 HYBRID (A)

Reg. Date: 12/11/2019 (Man. Year: 2019)

Colour: Grey

Engine Capacity: 1496 cc

Market Value/New Car Price: S\$80,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: LEB1452862

Chassis No: GP51343455

Odometer: 156213 km

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15

Front Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

Rear Tyre Size: 185/60 R15

Rear Left Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	0.00	4,000.00	-4,000.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>-4,000.00</b>	<b>4,000.00</b>	

**INSPECTION**

Date of Assignment: 15/08/2022 Present Location: Jin Auto Services Pte Ltd (Defu)

Date Inspected: 15/08/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Estimated Period of Repair: 0.0 days

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$80,000.00
OMV :	\$18,418.00
PARF Rebate (1) :	\$ 6,313.00
Quota Premium Paid :	\$40,009.00
COE Rebate (2) :	\$28,967.00
Total Rebate (1) + (2) = :	\$35,280.00

The total amount incurred will be Market Value \$80,000.00 minus Total Rebate \$35,280.00 = \$44,720.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2022)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ3674S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >