



Your Ref SNM22D205653/C01

Date: 04th October 2022

Our Ref : CS/CTI22007733/Ucy3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMQ 3674S
ACCIDENT ON 10/08/2022**

Instruction was received to inspect the vehicle Reg. No. SMQ 3674S. The inspection was conducted on 15/08/2022 at the premises of M/s Jin Auto Services Pte Ltd, Blk 14 Defu Lane 10 #01-412, Singapore 539195.

The following vehicle information was recorded:

Registration Number	: SMQ 3674S
Make/Model	: Honda Fit Hybrid 1.5 Auto
Year of Registration	: 2019
Body Colour	: Grey
Chassis Number	: GP51343455
Engine Capacity	: 1496 cc

The vehicle sustained damages at the front, n/s front & o/s front portion. The undercarriage affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 80,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 35,280.00)
Nett Liability	<u>S\$ 44,720.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.