



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8497G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RH TAILLAMP (N)	SCRATCHED	287.20	287.20
1	REAR BUMPER (N) (NPA)	TO REPAIR SEE LABOUR	-	-
1	RH REAR FENDER (N) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-28.72	-28.72
			258.48	258.48
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	STICKER WRAPPING (REAR FENDER RH) (SN)	NECESSARY	500.00	320.00
			500.00	320.00
	<b><u>LABOUR</u></b>			
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND RH REAR FENDER.		500.00	300.00
	TO SPRAY PAINT ON AFFECTED PORTIONS.		500.00	200.00
	TO CHECK AND RECONNECT NECESSARY WIRING.		25.00	20.00
			1,025.00	520.00
<b>GRAND TOTAL</b>			<b>1,783.48</b>	<b>1,098.48</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,098.48</b>

Report Ref No. CS/INC22007741/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.