

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI22007744/KCY3Q2**Date:** 31/10/2022REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SLN5343L**Insured Vehicle No :** GBB7950C

Date of Loss: 10/08/2022

Nature of Claim: TP

Claim No: DM22HO01367

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN5343L**

Make & Model: TOYOTA ESQUIRE, 1.8 HYBRID 7-SEATER GI CVT (A)

Engine No: 2ZR1902659

Reg. Date: 08/05/2017 (Man. Year: 2017)

Chassis No: ZWR800232912

Colour: Metallic Pearl White

Odometer: 73666 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,941.60	1,889.10	1,052.50	35.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,900.00	620.00	24.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,461.60	3,789.10	1,672.50	30.62
+ GST 7.00/7.00% (S\$)	382.31	265.24	117.07	30.62
Nett Amount (S\$)	5,843.91	4,054.34	1,789.57	30.62

INSPECTION

Date of Assignment: 15/08/2022 Present Location:

Ah Lim Motor Company (AMK)

Date Inspected: 16/08/2022 Inspected At:

Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2022)		
Parts:	M1-MPV	TOYOTA ESQUIRE 1.8 HYBRID 7-SEATER GI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN5343L)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR WINDSCREEN MLDG LH & RH	Not Necessary	60.00 F	*- F
2	1		*TAILGATE	Bent	550.00 F	*550.00 F
3	1		*TAILGATE ESQUIRE LOGO	Necessary	25.00 F	*25.00 F
4	1		*TAILGATE HYBRID SYNERGY DRIVE LOGO	Necessary	25.00 F	*25.00 F
5	1		*TAILGATE LOCK	Repair	180.00 F	*- F
6	1		*TAILGATE LOCK CATCH	Repair	20.00 F	*- F
7	1		*TAILGATE PULL HANDLE	Dented	20.00 F	*20.00 F
8	1		*TAILGATE INNER TRIM BTM	Serviceable	250.00 F	*- F
9	1		*TAILGATE RUBBER	Dented / Distorted	140.00 F	*140.00 F
10	1		*REAR BUMPER	Bent	295.00 F	*295.00 F
11	1		*REAR BUMPER TOW COVER LH	Cracked	12.00 F	*12.00 F
12	1		*REAR BUMPER REFLECTOR LH	Serviceable	25.00 F	*- F
13	1		*REAR BUMPER SIDE RETAINER LH	Distorted	60.00 F	*60.00 F
14	6		*REAR BUMPER CLIPS	Necessary	9.00 F	*9.00 F
15	1		*REAR ELECTRICAL KEY ANTENNA	Serviceable	40.00 F	*- F
16	1		*REAR END PANEL	Bent	260.00 F	*260.00 F
17	1		*REAR END PANEL GARNISH	Dented	85.00 F	*85.00 F
18	1		*REAR FLOOR TOP COVER	Serviceable	350.00 F	*- F
19	1		*REAR FLOOR MAT - CHECK PRICE	Serviceable	0.00 F	*- F
20	1		(NPA) *LUGGAGE COMPARTMENT TRIM BOX - CHECK PRICE	Serviceable	0.00 F	*- F
21	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
22	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
23	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
24	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,701.00	1,741.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	240.60	148.10
Total Parts (\$\$)	2,941.60	1,889.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	180.00	80.00
4	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	60.00	60.00
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	60.00	50.00
6	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00	60.00
7	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,000.00	700.00
8	TO SPRAY TAILGATE;REAR BUMPER;RR END PANEL; SPARE TYRE PANEL.	New	1,000.00	660.00
9	LABOUR TO RESET DIAGNOSTIC FAULT	New	-	150.00
Gross Labour Cost (\$\$)			2,520.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >