

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22007745/AQY3M4**Date:** 26/10/2022**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP316414
Claimant Vehicle No :	SKX446R	Insured Vehicle No :	SMX6213H
Date of Loss:	08/08/2022	Nature of Claim:	TP
		Claim No:	MPC03586/WF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX446R	Engine No:	0
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMGU643038
Reg. Date:	(Man. Year:)	Odometer:	91453 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Farroad 6 mm	Rear Left Side:	Farroad 6 mm
Front Right Side:	Farroad 6 mm	Rear Right Side:	Farroad 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,285.20	1,154.00	1,131.20	49.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	720.00	430.00	37.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,435.20	1,874.00	1,561.20	45.45
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,435.20	1,500.00	1,935.20	56.33

INSPECTION

Date of Assignment:	15/08/2022	AUTO UNITED SG PTE LTD (HQ) 13 KAKI BUKIT ROAD 4, #03-29 BARTLEY BIZ CENTRE, SINGAPORE 417807
Date Inspected:	16/08/2022 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX446R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	589.40 FL	*589.40 FL
2	1		*BUMPER LOWER DIFFUSER	Cracked	453.60 FL	*453.60 FL
3	1		*BUMPER REINTAINER L/R	Necessary	112.00 FL	*112.00 FL
4	1		*BUMPER BRACKET L/R	Not Necessary	140.00 FL	*- FL
5	1		*BUMPER REINFORCEMENT	Not Necessary	294.00 FL	*- FL
6	1		*BUMPER REFLECTOR L/R	Not Necessary	120.00 FL	*- FL
7	1		*END PANEL	Repair	455.00 FL	*- FL
8	1		*ENDPANEL TOP GARNISH	Not Necessary	102.00 FL	*- FL
9	1		*WEATHERSTRIP	Not Necessary	153.00 FL	*- FL
10	1		*BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
11	1		*END PANELTOP GARNIS CLIP	Not Necessary	50.00 FS	*- FS
12	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,769.00	1,385.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	483.80	231.00
Total Parts (\$\$)	2,285.20	1,154.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING	New	500.00	300.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO SPRAY TUFF COAT	New	100.00	40.00
Gross Labour Cost (\$)			1,150.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >