

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22007747/DQY3M4**Date:** 10/03/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001389813		
Claimant Vehicle No :	SMM4176C	Insured Vehicle No :	GBD327M		
Date of Loss:	12/08/2022	Nature of Claim:	TP	Claim No:	282132

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4176C	Engine No:	13107205N52B25AF
Make & Model:	BMW 325i, 2.5 CONVERTIBLE (A)	Chassis No:	WBAWL12040PD76695
Reg. Date:	14/10/2009 (Man. Year: 2009)	Odometer:	232509 km
Colour:	Bronze		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	265/30 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,071.27	4,647.79	21,423.48	82.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,300.00	2,120.00	61.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,491.27	5,947.79	23,543.48	79.83
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	29,491.27	4,500.00	24,991.27	84.74
+ GST 8.00/8.00% (S\$)	2,359.30	360.00	1,999.30	84.74
Nett Amount (S\$)	31,850.57	4,860.00	26,990.57	84.74

INSPECTION

Date of Assignment:	17/08/2022	
Date Inspected:	16/08/2022	Inspected At: JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Mar 2023)	
Parts:	N/A	BMW 325I 2.5 CONVERTIBLE (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM4176C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Not Necessary	2,348.55 FL	*- FL
2	1	*BONNET INSULATOR	Not Necessary	248.36 FL	*- FL
3	1	*BONNET SEAL	Not Necessary	101.50 FL	*- FL
4	1	*HEAD LAMP RH	Mtg Broken/Cracked	2,762.90 FL	*1,941.00 FL
5	1	*HEAD LAMP LOWER BRACKET RH	Mtg Cracked	369.15 FL	*198.70 FL
6	1	*HEAD LAMP ECU RH	Not Necessary	769.40 FL	*- FL
7	1	*HEAD LAMP WIRE HARNESS	Not Necessary	1,201.34 FL	*- FL
8	1	*FRONT BUMPER HEAD LAMP NOZZLE CAP RH	Serviceable	103.15 FL	*- FL
9	1	*FRONT BUMPER SIDE GRILLE RH	Serviceable	281.69 FL	*- FL
10	1	*FRONT BUMPER SENSOR	Not fitted	1,444.64 FL	*- FL
11	1	*FRONT BUMPER SENSOR HOLDER	Not fitted	261.56 FL	*- FL
12	1	*FRONT BUMPER SENSOR WIRE HARNESS	Not fitted	930.00 FL	*- FL
13	1	*FRONT BUMPER UNDER COVER	Not Necessary	228.95 FL	*- FL
14	2	*FRONT BUMPER SIDE RETAINER LH / RH @ \$295.14 EACH	Serviceable	590.28 FL	*- FL
15	1	*FRONT BUMPER SPONGE	Not Necessary	395.60 FL	*- FL
16	1	*FRONT REINFORCEMENT BAR	Not Necessary	1,065.12 FL	*- FL
17	1	*FRONT SUPPORT PANEL	Not Necessary	3,180.00 FL	*- FL
18	1	*FRONT FENDER RH	Mtg Broken	1,288.16 FL	*874.30 FL
19	1	*FRONT FENDER INNER SHIELD RH	Torn	195.44 FL	*195.44 FL
20	1	*FRONT FENDER LAMP CHROME GARNISH RH	Not Necessary	316.70 FL	*- FL
21	1	*FRONT GRILLE RH	Dislodged	782.00 FL	*147.55 FL
22	1	*FRONT BUMPER (M3 BODYKIT)	Cracked	3,000.00 FL	*1,235.00 FL
23	1	*HEAD LAMP STICKER	Necessary	400.00 FS	*80.00 FS
24	1	*TYRE	Not Necessary	600.00 FS	*- FS
25	1	*FRONT BUMPER LOWER LID (M3 BODYKIT)	Not fitted	2,000.00 FS	*- FS
26	1	*FRONT BUMPER STICKER WRAP	Necessary	600.00 FS	*200.00 FS
27	1	*FRONT FENDER STICKER WRAP	Necessary	600.00 FS	*200.00 FS
28	1	*FRONT BUMPER SIDE GRILLE	Not Necessary	1,000.00 FS	*- FS
29	1	*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
30	1	*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,164.49	5,106.99
- List Item Discount on L Items 5.00/10.00% (\$\$)	1,093.22	459.20
Total Parts (\$\$)	26,071.27	4,647.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	100.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,600.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,000.00	500.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	20.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	100.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			3,420.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >