Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

From: LKK Auto Consultants Pte Ltd 4 Shenton Way 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park #21-01 SGX Centre 2 Singapore 068807 Singapore 408933

Attn: Muhd Ashik B Madi 24 Feb 2023 Date:

Preliminary Advice

Insured Vehicle No : GBD327M

TP Vehicle No : SMM4176C : 12/08/2022 Accident Date Make : BMW 325I Assignment Date : 17/08/2022

Date of Inspection : 16/08/2022 Est. Duration of Repair

: JWG INTERNATIONAL PTE LTD (HQ) Inspection At

BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 29,491.27 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 5,947.79 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 5,947.79 |
| | | |
| Lump Sum Repair | :S\$ | 4,500.00 |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| () | The vehicle is economical for repair |
|-------|--|
| () | The vehicle is not economical for repair |
| () | Part-by-Part repair |
| (X) | Lump Sum repair |

The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (X) (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.