



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6682L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,250.00	-
1	FRONT BUMPER SIDE RETAINER N/S	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	50.00	-
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	820.00	-
1	HEADLAMP N/S	NOT NECESSARY	1,152.00	-
1	FRONT DOOR N/S	DENTED / BENT	1,455.20	1,315.00
1	FRONT DOOR HINGE N/S	NOT NECESSARY	145.00	-
1	FRONT DOOR INNER RUBBER N/S	NOT NECESSARY	220.00	-
1	SLIDING DOOR N/S	BADLY DENTED	1,850.20	1,660.00
1	SLIDING DOOR LOWER ROLLER BRACKET N/S	TWISTED	455.10	180.00
1	SLIDING DOOR INNER RUBBER N/S	NOT NECESSARY	220.00	-
1	ROCKER PANEL N/S	BENT / WARPED	990.00	910.00
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,815.00	-
1	REAR BUMPER	DEFORMED / TORN	1,250.00	1,080.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
	LESS 25% DISCOUNT		-	-1,298.75
			11,782.50	3,896.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT DOOR 'ROC' STICKER N/S (SN)	NECESSARY	50.00	30.00
1	REAR STEEL RIM N/S (SN)	TO REPAIR SEE LABOUR	180.00	-
1	REAR TYRE N/S (SN)	SERVICEABLE	200.00	-
			430.00	30.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR .		80.00	50.00
	TO TRANSFER FRONT DOOR MECHANISM .		80.00	60.00
	TO TRANSFER SLIDING DOOR MECHANISM .		80.00	60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	60.00
	TO SPRAY RUST PROOFING .		100.00	80.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT FENDER N/S ,REAR FENDER N/S AND REAR STEEL RIM N/S.		1,500.00	900.00
	TO PUTTY & SPRAY PAINTING.		1,600.00	1,100.00
			3,770.00	2,330.00
<b>GRAND TOTAL</b>			<b>15,982.50</b>	<b>6,256.25</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,000.00</b>

Report Ref No. CS/SMO22007748/Ucy3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.