

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007749/UVY3Q2**Date:** 05/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00087632100

Claimant Vehicle No : XD6150E **Insured Vehicle No :** YN5859L

Date of Loss: 06/08/2022 Nature of Claim: TP Claim No: SNM22D205615/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD6150E**

Make & Model: MAN TGM 18.280, 6.9 D 4X2 BB (M) Engine No: 21831875563190

Reg. Date: 03/09/2012 (Man. Year: 2012) Chassis No: WMAN08ZZXCXY283554

Colour: White Odometer: 480479 km

Engine Capacity: 6871 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: HILO 6 mm Rear Left Side: HILO 6/6 mm

Front Right Side: HILO 6 mm Rear Right Side: HILO 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,502.14	2,391.97	2,110.17	46.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	680.00	2,580.00	79.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,762.14	3,071.97	4,690.17	60.42
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	7,762.14	2,400.00	5,362.14	69.08
+ GST 7.00/7.00% (S\$)	543.35	168.00	375.35	69.08
Nett Amount (S\$)	8,305.49	2,568.00	5,737.49	69.08

INSPECTION

Date of Assignment: 17/08/2022

Date Inspected: 16/08/2022 Inspected At: Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Oct 2022)	
Parts:	N/A	MAN TGM 18.280 6.9 D 4X2 BB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD6150E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ASSY -RH	Bent / Twisted	2,438.12 F	*2,438.12 FL
2	1		*FRONT DOOR HINGE UPPER -RH	Not Necessary	134.50 F	*- FL
3	1		*FRONT DOOR HINGE LOWER -RH	Not Necessary	134.50 F	*- FL
4	1		*FRONT CORNER PANEL OUTER -RH	Cracked	219.62 F	*219.62 FL
5	1		*FRONT CORNER PANEL INNER -RH	Repair	335.00 F	*- FL
6	1		*SIDE MIRROR ASSY -RH (CUT)	Not Consistent With The Impact	1,220.26 F	*- FL
7	1		*SIDE MIRROR BRACKER LOWER -RH	Not Necessary	20.14 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	4,502.14 2,657.74
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 265.77
					Total Parts (S\$)	4,502.14 2,391.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RENEW CORNER PANEL ,FRONT DOOR ASSY RH ,SIDE MIRROR ASSY	New	980.00	300.00
2	TO SPRAY & PAINTING ON AFFECTED AREA	New	1,800.00	350.00
3	TO RUST PROOFING	New	480.00	30.00
Gross Labour Cost (\$)			3,260.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >