



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 8972K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	HANDLE ASSY-DOOR OUTSIDE (SN)	CRACKED	66.00	66.00
1	COVER-FR DR O/S HDL (SN)	NOT NECESSARY	24.00	-
1	PAD-DOOR OUTSIDE HANDLE, FR (SN)	NECESSARY	1.00	1.00
1	PAD-DOOR OUTSIDE HANDLE, RR (SN)	NOT NECESSARY	1.00	-
1	LAMP ASSY-OUTSIDE MIRROR, RH (SN)	CRACKED	133.00	133.00
			275.00	220.00
	<b><u>LABOUR</u></b>			
	REPLACE RH WING MIRROR ASSY, FRT RH DOOR HANDLE & AFFECTED AREA. REPAIR ON FRT RH DOOR.		1,920.00	640.00
	PAINT WORK ON FRT RH DOOR & RH WING MIRROR COVER.		1,100.00	650.00
	PERFORM RUST PREVENTION.	NOT NECESSARY	100.00	-
	TO APPLY SEALANT ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.		150.00	120.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00	280.00
			3,650.00	1,690.00
	<b>GRAND TOTAL</b>		<b>3,925.00</b>	<b>1,910.00</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>1,910.00</b>

Report Ref No. CS/GAI22007753/Rcy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.