



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 7939B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	BUCKLED	954.50	945.00
2	REAR BUMPER SIDE RETAINER LH & RH	SERVICEABLE	45.60	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	53.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	53.00	-
1	REAR BUMPER LOWER (NPA)	SERVICEABLE	-	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	656.00	-
1	REAR END PANEL GARNISH	SERVICEABLE	57.60	-
1	REAR BOOT	BENT	982.00	982.00
1	REAR BOOT LOCK (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR REINFORCEMENT BAR (NPA)	SERVICEABLE	-	-
2	REAR REINFORCEMENT ARM (NPA)	SERVICEABLE	-	-
1	REAR EXHAUST TIP (NPA)	SERVICEABLE	-	-
1	REAR EXHAUST HEAT HIELD (NPA)	SERVICEABLE	-	-
1	REMOTE CONTROL SENSOR	CRACKED	126.00	126.00
	LESS 20% DISCOUNT		-585.54	-410.60
			2,342.16	1,642.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
2	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	70.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	SET REAR BOOT INSULATOR CLIPS (SN)	NOT NECESSARY	45.00	-
			510.00	245.00
<b><u>LABOUR</u></b>				
	SPRAY PAINT ON ALL AFFECTED AREA.		1,000.00	600.00
	LABOUR REMOVE /REFIX ACCIDENT DAMAGE PARTS TO KNOCK ,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR BOOT LOCK .		1,000.00	350.00
	TO CHECK WIRING SYSTEM & LIGHT.		120.00	15.00
	TO APPLY ANTI RUST TREATMENT.	NOT NECESSARY	120.00	-

Report Ref No. CS/AGI22007755/Kvy3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REPLACE REAR REVERSE SENSOR .		180.00	50.00
			2,420.00	1,015.00
GRAND TOTAL			5,272.16	2,902.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/AGI22007755/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.