

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS4/CTI22007763/AQY3E2**Date:** 28/12/2022**REFERENCE**Insured/Claimant: LIM HOCK SENG Policy No: DMPCSNW00202242101
Date of Loss: 11/08/2022 Nature of Claim: OD Claim No: SNM22D205619/C01/CHNGPW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJQ26T**
Make & Model: LEXUS RX, 300 LUXURY (A) Engine No: 8ARW936420
Reg. Date: 17/10/2018 (Man. Year: 2018) Chassis No: JTJZAMCA302048609
Colour: White Odometer: 125304 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$182,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,107.00	32,141.20	6,965.80	17.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,270.00	3,600.00	2,670.00	42.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,377.00	35,741.20	9,635.80	21.23
Approved Total (Overridden) (S\$)		28,600.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	44,627.00	27,850.00	16,777.00	37.59
+ GST 7.00/7.00% (S\$)	3,123.89	1,949.50	1,174.39	37.59
Nett Amount (S\$)	47,750.89	29,799.50	17,951.39	37.59

INSPECTIONDate of Assignment: 15/08/2022
Date Inspected: 15/08/2022 Inspected At: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18
Singapore 417921
Estimated Period of Repair: 16.0 days**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts: M1-SUV	LEXUS RX 300 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJQ26T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE LH SIDE UNDER COVER (WCP)	Deformed	120.00 F	*120.00 F
2	1		*ENGINE LH UNDER COVER (WCP)	Deformed	180.00 F	*180.00 F
3	1		*FRONT BONNET (WCP)	Dented	1,200.00 F	*1,200.00 F
4	2		*FRONT BONNET DAMPER L/R (WCP)	Not Necessary	320.00 F	*- F
5	2		*FRONT BONNET HINGES L/R (WCP)	Bent	110.00 F	*110.00 F
6	1		*FRONT BONNET INSULATOR MAT (WCP)	Not Necessary	260.00 F	*- F
7	8		*FRONT BONNET INSULATOR MAT CLIPS (WCP)	Not Necessary	24.00 F	*- F
8	1		*FRONT BONNET RUBBER SEAL (WCP)	Necessary	55.00 F	*55.00 F
9	1		*FRONT BUMPER (WCP)	Distorted	420.00 F	*420.00 F
10	1		*FRONT BUMPER INNER SPONGE (WCP)	Cracked	95.00 F	*95.00 F
11	1		*FRONT BUMPER LH FOG LAMP (WCP)	Missing	330.00 F	*330.00 F
12	1		*FRONT BUMPER LH FOG LAMP COVER (WCP)	Missing	120.00 F	*120.00 F
13	1		*FRONT BUMPER LH FOG LAMP COVER CHROME MOULDING (WCP)	Missing	280.00 F	*280.00 F
14	1		*FRONT BUMPER LH INNER AIR GUIDE (LOWER) (WCP)	Cracked	90.00 F	*90.00 F
15	1		*FRONT BUMPER LH INNER AIR GUIDE (TOP) (WCP)	Cracked	90.00 F	*90.00 F
16	1		*FRONT BUMPER LH SIDE COVER (WCP)	Distorted	60.00 F	*60.00 F
17	1		*FRONT BUMPER LH SIDE LOWER LID GARNISH (WCP)	Distorted	250.00 F	*250.00 F
18	1		*FRONT BUMPER LOWER CENTER LID GARNISH (WCP)	Distorted	180.00 F	*180.00 F
19	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	320.00 F	*320.00 F
20	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING (WCP)	Cracked	330.00 F	*330.00 F
21	1		*FRONT BUMPER LOWER GRILLE LH COVER (WCP)	Cracked	35.00 F	*35.00 F
22	1		*FRONT BUMPER LOWER UNDER COVER (WCP)	Torn	200.00 F	*200.00 F
23	2		*FRONT BUMPER PARKING SENSOR (WCP)	Missing (1Pc), Damaged (1Pc)	420.00 F	*420.00 F
24	2		*FRONT BUMPER PARKING SENSOR O RING (WCP)	Necessary	56.00 F	*56.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	4		*FRONT BUMPER PARKING SENSOR HOLDER BRACKET (WCP)	Necessary	112.00 F	*112.00 F
26	1		*FRONT BUMPER PARKING SENSOR WIRE HARNESS (WCP)	Snapped	380.00 F	*380.00 F
27	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	270.00 F	*- F
28	1		*FRONT BUMPER SIDE RETAINER L/R (WCP)	N/S Damaged	116.00 F	*58.00 F
29	1		*FRONT ENGINE CROSS MEMBER (WCP)	Bent	1,600.00 F	*1,600.00 F
30	1		*FRONT ENGINE CROSS MEMBER BRACKET LH (FRONT) (WCP)	Bent	160.00 F	*160.00 F
31	1		*FRONT ENGINE CROSS MEMBER BRACKET LH (REAR) (WCP)	Bent	160.00 F	*160.00 F
32	2		*FRONT ENGINE CROSS MEMBER MOUNTING (FRONT) (WCP)	Not Necessary	200.00 F	*- F
33	2		*FRONT ENGINE CROSS MEMBER MOUNTING (REAR) (WCP)	Not Necessary	200.00 F	*- F
34	1		*FRONT GRILLE (WCP)	Cracked	760.00 F	*760.00 F
35	1		*FRONT GRILLE LOGO EMBLEM (WCP)	Necessary	180.00 F	*180.00 F
36	1		*FRONT GRILLE CHROME MOULDING (WCP)	Cracked	370.00 F	*370.00 F
37	1		*FRONT GRILLE UPPER RUBBER SEAL (WCP)	Not Necessary	78.00 F	*- F
38	1		*FRONT GRILLE UPPER TOP COVER (WCP)	Not Necessary	175.00 F	*- F
39	2		*FRONT HEADLAMP L/R (WCP)	Cracked	3,110.00 F	*3,110.00 F
40	1		*FRONT HEADLAMP PANEL (WCP)	Distorted	650.00 F	*650.00 F
41	1		*FRONT LH ABS SENSOR (WCP)	Not Necessary	210.00 F	*- F
42	1		*FRONT LH AUTO COOLER (WCP)	Distorted	450.00 F	*450.00 F
43	1		*FRONT LH AUTO COOLER AIR DUCT (WCP)	Distorted	180.00 F	*180.00 F
44	1		*FRONT LH AUTO COOLER BRACKET (WCP)	Bent	200.00 F	*200.00 F
45	1		*FRONT LH CONVERTER UNIT (WCP)	Dented	850.00 F	*850.00 F
46	1		*FRONT LH DOOR (WCP)	Repair	560.00 F	*- F
47	1		*FRONT LH DOOR FRAME STICKER (NO:1) (WCP)	Not Necessary	60.00 F	*- F
48	1		*FRONT LH DOOR FRAME STICKER (NO:2) (WCP)	Not Necessary	60.00 F	*- F
49	1		*FRONT LH DOOR FRAME STICKER (NO:3) (WCP)	Not Necessary	60.00 F	*- F
50	1		*FRONT LH DOOR PROTECTOR GARNISH (WCP)	Not Necessary	200.00 F	*- F
51	8		*FRONT LH DOOR UPPER MOULDING RIVET (WCP)	Not Necessary	24.00 F	*- F
52	1		*FRONT LH DOOR VERTICAL GARNISH (WCP)	Not Necessary	120.00 F	*- F
53	1		*FRONT LH DOOR WEATHER STRIP SEAL (WCP)	Not Necessary	105.00 F	*- F
54	1		*FRONT LH DRIVE SHAFT (WCP)	Bent	820.00 F	*820.00 F
55	1		*FRONT LH FENDER (WCP)	Distorted	440.00 F	*440.00 F
56	1		*FRONT LH FENDER ARCH MOULDING (WCP)	Missing	185.00 F	*185.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
57	1		*FRONT LH FENDER INNER COVER (WCP)	Not Necessary	75.00 F	*- F
58	1		*FRONT LH FENDER INNER PANEL (WCP)	Repair	370.00 F	*- F
59	1		*FRONT LH FENDER INNER PANEL TOP COVER (WCP)	Deformed	180.00 F	*180.00 F
60	1		*FRONT LH FENDER INNER SHIELD (WCP)	Torn	200.00 F	*200.00 F
61	1		*FRONT LH FENDER QUARTER GARNISH (WCP)	Not Necessary	75.00 F	*- F
62	1		*FRONT LH FENDER SIDE BRACKET (WCP)	Bent	65.00 F	*65.00 F
63	1		*FRONT LH FENDER WHEEL HOUSE (WCP)	Distorted	420.00 F	*420.00 F
64	1		*FRONT LH FUSE BOX CASING (WCP)	Cut	380.00 F	*380.00 F
65	1		*FRONT LH FUSE BOX TRAY (WCP)	Cracked	200.00 F	*200.00 F
66	1		*FRONT LH FUSE BOX WIRE HARNESS ASSY (WCP)	Snapped	2,900.00 F	*2,900.00 F
67	1		*FRONT LH HEADLAMP CONTROL UNIT (WCP)	Damaged	480.00 F	*480.00 F
68	1		*FRONT LH KNUCKLE ARM (WCP)	Damaged	350.00 F	*350.00 F
69	1		*FRONT LH KNUCKLE ARM BEARING (WCP)	Damaged	110.00 F	*110.00 F
70	1		*FRONT LH LINKAGE (WCP)	Bent	80.00 F	*80.00 F
71	1		*FRONT LH LOWER ARM (WCP)	Bent	240.00 F	*240.00 F
72	1		*FRONT LH LOWER ARM BALL JOINT (WCP)	Damaged	125.00 F	*125.00 F
73	1		*FRONT LH SHOCK ABSORBER (WCP)	Bent	300.00 F	*300.00 F
74	1		*FRONT LH SHOCK ABSORBER MOUNTING BEARING (WCP)	Not Necessary	80.00 F	*- F
75	1		*FRONT LH SHOCK ABSORBER MOUNTING RUBBER (WCP)	Not Necessary	60.00 F	*- F
76	1		*FRONT LH SHOCK ABSORBER MOUNTING SPONGE (WCP)	Not Necessary	70.00 F	*- F
77	1		*FRONT LH SPORT RIM (WCP)	Cut	2,500.00 F	*2,000.00 F
78	1		*FRONT LH STEERING TIE ROD END (WCP)	Not Necessary	105.00 F	*- F
79	1		*FRONT LH WHEEL HUB (WCP)	Damaged	330.00 F	*330.00 F
80	1		*FRONT LH WIPER BLADE (WCP)	Not Necessary	85.00 F	*- F
81	1		*FRONT STABILIZER BAR (WCP)	Not Necessary	320.00 F	*- F
82	1		*FRONT STEERING RACK & PINION (WCP)	Not Necessary	1,800.00 F	*- F
83	1		*FRONT WINDSCREEN GLASS (WCP)	Cracked	1,050.00 F	*1,050.00 F
84	1		*FRONT WINDSCREEN GLASS SEAL (WCP)	Necessary	75.00 F	*75.00 F
85	2		*FRONT WINDSCREEN GLASS SIDE MOULDING L/R (WCP)	Necessary	170.00 F	*170.00 F
86	1		*FRONT WIPER GRILLE GARNISH (WCP)	Cut	290.00 F	*290.00 F
87	1		*REAR LH DOOR (WCP)	Dented	750.00 F	*750.00 F
88	1		*REAR LH DOOR ARCH GARNISH (WCP)	Not Necessary	95.00 F	*- F
89	1		*FRONT LH DOOR ARCH RUBBER SEAL (WCP)	Not Necessary	105.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	1		*REAR LH DOOR FRAME STICKER (NO:1) (WCP)	Necessary	57.00 F	*57.00 F
91	1		*REAR LH DOOR FRAME STICKER (NO:2) (WCP)	Necessary	57.00 F	*57.00 F
92	1		*REAR LH DOOR FRAME STICKER (NO:3) (WCP)	Necessary	57.00 F	*57.00 F
93	1		*REAR LH DOOR INNER TRIM BOARD (WCP)	Not Necessary	900.00 F	*- F
94	1		*REAR LH DOOR PROTECTOR GARNISH (WCP)	Deformed	220.00 F	*220.00 F
95	7		*REAR LH DOOR UPPER MOULDING RIVET (WCP)	Not Necessary	21.00 F	*- F
96	1		*REAR LH DOOR VERTICAL GARNISH (WCP)	Not Necessary	120.00 F	*- F
97	1		*REAR LH DOOR WEATHER STRIP (WCP)	Not Necessary	110.00 F	*- F
98	1		*REAR LH SPORT RIM (WCP)	Cut	2,500.00 F	*2,000.00 F
99	1		*REAR LH WHEEL BEARING (WCP)	Not Necessary	360.00 F	*- F
100	1		*FRONT LH SHOCK ABSORBER MOUNTING (WCP)	Not Necessary	100.00 F	*- F
101	1		*AUTO OIL	Necessary	200.00 FS	*80.00 FS
102	1		*BATTERY ASSY	Not Necessary	250.00 FS	*- FS
103	1		*SET FRONT GRILLE UPPER TOP COVER CLIPS	Not Necessary	50.00 FS	*- FS
104	1		*FRONT LH DOOR PROTECTOR GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
105	1		*SET FRONT LH FENDER ARCH GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
106	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
107	1		*FRONT LH TYRE	Cut	350.00 FS	*300.00 FS
108	1		*FRONT WINDSCREEN GLASS E.R.P BRACKET	Necessary	25.00 FS	*25.00 FS
109	1		*FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER	Necessary	15.00 FS	*15.00 FS
110	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
111	1		*SET REAR LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
112	1		*SET FRONT LH DOOR PROTECTOR GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
113	1		*REAR LH TYRE	Not Necessary	350.00 FS	*- FS
114	1		*SET REAR LH DOOR ARCH GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	39,107.00	29,272.00
+ Margin on L,N Items 0.00/10.00% (\$\$)	0.00	2,869.20
Total Parts (\$\$)	39,107.00	32,141.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS. (TO FR)	New	150.00	120.00
2	TO RESET SYSTEM AFTER REPAIR WORKS	New	280.00	180.00
3	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	400.00	100.00
4	TO REMOVE, CHANGE WINDSCREEN	New	150.00	120.00
5	TO REMOVE, INSTALL ENGINE WITH TRANSMISSION (TO FR)	New	400.00	0.00
6	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	400.00	320.00
7	TO REMOVE, REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR)	New	150.00	0.00
8	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
9	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	160.00	80.00
10	TO REMOVE, REINSTALL DASHBOARD FASCIA, METER READING AND ETC (TO FR)	New	280.00	0.00
11	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
12	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	1,400.00
Gross Labour Cost (\$)			6,270.00	3,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >