

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE			Ref:	CS3/ASM22007765/Gvy3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	22/08/2022	
	ATTN: KHOR SAW	THENG	(Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMN 7308P	Veh. Inspected		SND 1260Y	
	Policy No.	P2345769	Coverage (\$)		0.00	
	Claim No.	S2M048SS	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		15/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ CLA180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	WDD1173422N634451	Colour		SILVER	
	Odometer	48662 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/40 ZR18	MICHELIN		6 mm	
	L/H Front Tyre	225/40 ZR18	MICHELIN		6 mm	
	R/H Rear Tyre	225/40 ZR18	MICHELIN		6 mm	
	L/H Rear Tyre	225/40 ZR18	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
5.	5. General Information					
	Accident Date	11/08/2022	Inspect Date / Ti	ime	17/08/2022 (10:00 AM)	
	Survey held at	QAS AUTO PTE LTD				
		3018A UBI ROAD 1 #01-23 SINGAPORE 408711				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22007765/Gvy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor