

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22007772/APA3Q2**Date:** 04/11/2022**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLF4539M**Insured Vehicle No :** SLH4056D

Date of Loss: 03/08/2022

Nature of Claim: TP Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLF4539M**

Make &amp; Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4033423

Reg. Date: 26/08/2016 (Man. Year: 2016)

Chassis No: RU11113420

Colour: Black

Odometer: 199289 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,861.36	3,160.08	4,701.28	59.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	760.00	2,670.00	77.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,291.36</b>	<b>3,920.08</b>	<b>7,371.28</b>	<b>65.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	11,291.36	3,100.00	8,191.36	72.55
<b>+ GST 7.00/7.00% (S\$)</b>	790.40	217.00	573.40	72.55
<b>Nett Amount (S\$)</b>	<b>12,081.76</b>	<b>3,317.00</b>	<b>8,764.76</b>	<b>72.55</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 15/08/2022

Date Inspected: 17/08/2022 Inspected At:

Sm Automotive - Kaki Bukit (HQ)  
BLOCK C - 1, KAKI BUKIT AVE 6, #01-43  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2022)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF4539M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	872.00 FL	*872.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	560.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT GARNISH LH	Not Necessary	56.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	24.00 FL	*24.00 FL
5	1		*FRONT BUMPER TOW COVER	Not Necessary	42.00 FL	*- FL
6	1		*FRONT BUMPER LOWER LIP	Torn	462.00 FL	*386.00 FL
7	1		*FRONT BUMPER LOWER LIP RUBBER	Not Necessary	126.00 FL	*- FL
8	1		*FRONT BUMPER UNDER COVER GARNISH	Not Necessary	106.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	210.00 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	362.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP OUTER GARNISH LH	Not Necessary	162.00 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP BRACKET LH	Not Necessary	98.00 FL	*- FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH RH	Not Necessary	112.00 FL	*- FL
14	1		*FRONT SUPPORT PANEL SIDE GARNISH RH	Not Necessary	84.00 FL	*- FL
15	1		*FRONT HEADLAMP LH	Cracked	1,999.00 FL	*1,784.00 FL
16	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	56.00 FL	*- FL
17	1		*FRONT HEADLAMP WIRE HARNESS	Not Necessary	711.30 FL	*- FL
18	1		*FRONT FENDER RH	Not Necessary	389.00 FL	*- FL
19	1		*FRONT FENDER OUTER GARNISH LH	Cut	183.60 FL	*183.60 FL
20	1		*FRONT FENDER INNER SHIELD RH	Deformed	113.00 FL	*113.00 FL
21	1		*FRONT LOWER ARM LH	Not Necessary	654.50 FL	*- FL
22	1		*FRONT SHOCK ABSORBER LH	Not Necessary	389.60 FL	*- FL
23	1		*FRONT KNUCKLE ARM LH	Not Necessary	489.10 FL	*- FL
24	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	215.60 FL	*- FL
25	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*FRONT FENDER OUTER GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
28	1		*FRONT SPORT RIM RH	Cut	650.00 FS	*400.00 FS
29	1		*FRONT TYRE RH	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,556.70</b>	<b>3,832.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,695.34	672.52
<b>Total Parts (\$)</b>	<b>7,861.36</b>	<b>3,160.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING	New	1,500.00	400.00
2	LABOUR FOR SPRAYPAINTING	New	1,200.00	250.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	300.00	0.00
5	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE	New	200.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
			<b>Gross Labour Cost (\$)</b>	<b>760.00</b>
			<b>3,430.00</b>	<b>3,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >