

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22007774/RPA3Q2**Date:** 04/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210023697
Claimant Vehicle No :	SHC4907Y	Insured Vehicle No :	SMZ3280Y
Date of Loss:	26/07/2022	Nature of Claim:	TP
		Claim No:	2082392140SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4907Y		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6575837
Reg. Date:	05/02/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U805767314
Colour:	Maroon	Odometer:	727220 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,677.31	850.68	1,826.63	68.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,812.00	640.00	1,172.00	64.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,489.31	1,490.68	2,998.63	66.79
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	4,489.31	1,300.00	3,189.31	71.04
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	05/08/2022	
Date Inspected:	05/08/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH (DISC 10%)	Scratched	945.20 F	*850.68 F
2	1		*BUMPER CLIPS	Not Necessary	1.61 F	*- F
3	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
4	1		*NAME PLATE (HYBRID)	Not Necessary	51.90 F	*- F
5	1		*FENDER LINER FRT/LH	Not Necessary	171.70 F	*- F
6	1		*FENDER PROTECTOR FRT/LH UPPER	Not Necessary	46.10 F	*- F
7	1		*PROTECTOR FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F
8	1		*SEAL FRONT FENDER TO COWL SIDE LH	Not Necessary	15.20 F	*- F
9	1		*FENDER LINER PAD FR WHEEL LH	Not Necessary	49.30 F	*- F
10	1		*FENDER FRT/LH	Repair	723.40 F	*- F
11	1		*BUMPER FRT	Repair	482.00 F	*- F
					Total Parts (\$)	2,677.31 850.68

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	756.00	400.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	40.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			1,812.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >