

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22007784/KPA3Q2**Date:** 23/06/2023**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210096278   |
| <b>Claimant Vehicle No :</b> | SHC5436H                             | <b>Insured Vehicle No :</b> | GBH7135H     |
| Date of Loss:                | 11/08/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 5988584172SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                     |             |                   |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHC5436H</b>                     |             |                   |
| Make & Model:               | TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) | Engine No:  | 2ZR2H10824        |
| Reg. Date:                  | 13/09/2021 (Man. Year: 2020)        | Chassis No: | JTDKB3FU803092472 |
| Colour:                     | Metallic Pearl White/Red            | Odometer:   | 117458 km         |
| Engine Capacity:            | 1798 cc                             |             |                   |
| Market Value/New Car Price: | N/A                                 |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>   |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |            |                  |                 |
|-------------------|------------|------------------|-----------------|
| Front Tyre Size:  | 195/65 R15 | Rear Tyre Size:  | 195/65 R15      |
| Front Left Side:  | Wanli 7 mm | Rear Left Side:  | LANVIGATOR 9 mm |
| Front Right Side: | Wanli 7 mm | Rear Right Side: | LANVIGATOR 9 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 5,909.72          | 2,226.55          | 3,683.17          | 62.32         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 5,100.00          | 690.00            | 4,410.00          | 86.47         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                        | <b>11,009.72</b>  | <b>2,916.55</b>   | <b>8,093.17</b>   | <b>73.51</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 770.68            | 204.16            | 566.52            | 73.51         |
| <b>Nett Amount (S\$)</b>                        | <b>11,780.40</b>  | <b>3,120.71</b>   | <b>8,659.69</b>   | <b>73.51</b>  |
| <b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b> |                   | 100.00            |                   |               |
| <b>+ Car Rental (2.0 x S\$113.42/day) (S\$)</b> |                   | 226.84            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>3,455.00</b>   |                   |               |

**INSPECTION**

|                             |            |               |                                                                                  |
|-----------------------------|------------|---------------|----------------------------------------------------------------------------------|
| Date of Assignment:         | 15/08/2022 |               |                                                                                  |
| Date Inspected:             | 15/08/2022 | Inspected At: | Trans-cab Auto Services Pte Ltd<br>No 2 Ang Mo Kio Street 63<br>Singapore 569111 |
| Estimated Period of Repair: | 2.0 days   |               |                                                                                  |

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition        | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------------------|------------------|-------------|------------|
| 1   | 1   |          | *COVER ,REAR BUMPER                       | Buckled / Dented | 485.60 FL   | *485.60 FL |
| 2   | 1   |          | *REINFORCEMENT SUB-ASSY ,REAR BUMPER      | Bent             | 332.70 FL   | *332.70 FL |
| 3   | 1   |          | *GUARD ,REAR BUMPER ,CENTER               | Bent             | 374.50 FL   | *374.50 FL |
| 4   | 1   |          | *SEAL ,REAR BUMPER SIDE ,RH               | Serviceable      | 118.30 FL   | *- FL      |
| 5   | 1   |          | *RETAINER ,REAR BUMPER SIDE ,RH           | Serviceable      | 132.60 FL   | *- FL      |
| 6   | 1   |          | *COVER ,REAR BUMPER LOWER                 | Missing          | 22.00 FL    | *22.00 FL  |
| 7   | 1   |          | *COVER ,DECK TRIM ,REAR                   | Serviceable      | 126.70 FL   | *- FL      |
| 8   | 1   |          | *PANEL SUB-ASSY ,BODY LOWER BACK          | Repair           | 651.00 FL   | *- FL      |
| 9   | 1   |          | *REFLECTOR ASSY ,REFLEX RH                | Serviceable      | 39.00 FL    | *- FL      |
| 10  | 1   |          | *COVER ,FLOOR UNDER NO2 (RH)              | Serviceable      | 241.90 FL   | *- FL      |
| 11  | 1   |          | *COVER ,FLOOR UNDER NO1 (LH)              | Serviceable      | 175.10 FL   | *- FL      |
| 12  | 1   |          | *COVER REAR FLOOR (CTR)                   | Cracked          | 229.90 FL   | *229.90 FL |
| 13  | 1   |          | *PANEL SUB-ASSY BACK DOOR                 | Repair           | 1,147.80 FL | *- FL      |
| 14  | 1   |          | *PLATE LUGGAGE COMPARTMENT DOOR NAME NO.2 | Necessary        | 54.60 FL    | *54.60 FL  |
| 15  | 1   |          | *PLATE ,BACK DOOR NAME NO.1               | Necessary        | 54.60 FL    | *54.60 FL  |
| 16  | 1   |          | *ORNAMENT SUB-ASSY ,BACK DOOR             | Necessary        | 47.90 FL    | *47.90 FL  |
| 17  | 1   |          | *GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE     | Mtg Cracked      | 913.60 FL   | *913.60 FL |
| 18  | 1   |          | *BOARD ASSY ,BACK DOOR TRIM               | Serviceable      | 259.20 FL   | *- FL      |
| 19  | 1   |          | *WEATHERSTRIP BACK DOOR                   | Serviceable      | 372.30 FL   | *- FL      |
| 20  | 1   |          | *STAY ASSY ,BACK DOOR ,LH                 | Serviceable      | 242.50 FL   | *- FL      |
| 21  | 1   |          | *STAY ASSY ,BACK DOOR ,RH                 | Serviceable      | 242.50 FL   | *- FL      |
| 22  | 1   |          | *HINGE ASSY BACK DOOR ,LH                 | Repair           | 61.00 FL    | *- FL      |
| 23  | 1   |          | *HINGE ASSY BACK DOOR ,RH                 | Repair           | 61.00 FL    | *- FL      |
| 24  | 1   |          | *REAR BUMPER SIDE CLIP                    | Not Necessary    | 60.00 FS    | *- FS      |
| 25  | 1   |          | *BOOT STICKER TRANSCAB                    | Necessary        | 100.00 FS   | *30.00 FS  |
| 26  | 1   |          | *BOOT STICKER TEL NO                      | Necessary        | 100.00 FS   | *30.00 FS  |
| 27  | 1   |          | *SET PARKING AID                          | Dented           | 700.00 FS   | *220.00 FS |
| 28  | 1   |          | *SET REAR BUMPER CLIP                     | Necessary        | 85.00 FS    | *60.00 FS  |
| 29  | 1   |          | *REAR BUMPE RETAINER CLIP                 | Not Necessary    | 75.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |          |          |
|-----------------------------------------------------|----------|----------|
| Sub Total (\$\$)                                    | 7,506.30 | 2,855.40 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,596.58 | 628.85   |
| Total Parts (\$\$)                                  | 5,909.72 | 2,226.55 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                              | Lab.Type | Repairer's      | Amount        |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------|----------|-----------------|---------------|
| <b>Labour Items</b>             |                                                                                                                          |          |                 |               |
| 1                               | TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS                                                              | New      | 240.00          | 0.00          |
| 2                               | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR                              | New      | 380.00          | 0.00          |
| 3                               | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New      | 1,600.00        | 200.00        |
| 4                               | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR                                         | New      | 380.00          | 0.00          |
| 5                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                         | New      | 1,600.00        | 440.00        |
| 6                               | TO REINSTALL REAR BUMPER PARKING SENSOR                                                                                  | New      | 170.00          | 50.00         |
| 7                               | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING                                                                          | New      | 170.00          | 0.00          |
| 8                               | TO CHECK ELECTRICAL LIGHTING CONCERNED                                                                                   | New      | 170.00          | 0.00          |
| 9                               | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT                                                                  | New      | 220.00          | 0.00          |
| 10                              | TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST                                   | New      | 170.00          | 0.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                          |          | <b>5,100.00</b> | <b>690.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >