

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007785/UCY3E2**Date:** 11/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00013012203

Claimant Vehicle No : XE6894L **Insured Vehicle No :** XD5413D

Date of Loss: 11/08/2022 Nature of Claim: TP Claim No: SNM22D205654/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE6894L**

Make & Model: HINO FS1EKND, 12.9 D 28 TON 6X4 MT (M) Engine No: E13CBN10209

Reg. Date: 26/11/2021 (Man. Year: 2021) Chassis No: JHDFS1EKKXXX10031

Colour: White Odometer: 57728 km

Engine Capacity: 12913 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Centara 7 mm Rear Left Side: Centara 7/7 mm

Front Right Side: Centara 7 mm Rear Right Side: Centara 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,907.05	7,001.21	3,905.84	35.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,800.00	1,480.00	45.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,187.05	8,801.21	5,385.84	37.96
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	14,187.05	7,000.00	7,187.05	50.66
+ GST 7.00/7.00% (S\$)	993.09	490.00	503.09	50.66
Nett Amount (S\$)	15,180.14	7,490.00	7,690.14	50.66

INSPECTION

Date of Assignment: 15/08/2022

Date Inspected: 17/08/2022 Inspected At: Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Oct 2022)	
Parts:	N/A	HINO FS1EKND 12.9 D 28 TON 6X4 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE6894L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR (ROUND) N/S	Broken	319.48 FL	*319.48 FL
2	1		*SIDE MIRROR (B) N/S	Not Necessary	283.50 FL	*- FL
3	1		*SIDE MIRROR (S) N/S	Not Necessary	245.00 FL	*- FL
4	1		*SIDE MIRROR STAY N/S	Bent / Twisted	999.04 FL	*999.04 FL
5	1		*SIDE MIRROR STAY LOWER N/S	Bent	163.10 FL	*163.10 FL
6	1		*SIDE MIRROR STAY LOWER COVER N/S	Not Necessary	23.24 FL	*- FL
7	1		*SIDE MIRROR STAY LOWER COVER N/S	Not Necessary	23.24 FL	*- FL
8	1		*SIDE MIRROR STAY LOWER COVER N/S	Not Necessary	35.28 FL	*- FL
9	1		*SIDE MIRROR STAY TOP BRACKET N/S	Bent	399.84 FL	*399.84 FL
10	1		*SIDE MIRROR STAY TOP BRACKET SUPPORT N/S	Not Necessary	2.52 FL	*- FL
11	1		*SIDE MIRROR MOTOR ASSY N/S	Cracked / Jammed	1,366.96 FL	*1,366.96 FL
12	1		*FRONT GRILLE HINO EMBLEM	Necessary	266.86 FL	*266.86 FL
13	1		*FRONT GRILLE PANEL NO.1	Cracked	662.06 FL	*662.06 FL
14	1		*FRONT GRILLE PANEL NO.2	Cracked	532.42 FL	*532.42 FL
15	1		*FRONT GRILLE PANEL NO.3	Cracked	372.68 FL	*372.68 FL
16	1		*FRONT GRILLE PANEL NO.4.1	Cut	136.22 FL	*136.22 FL
17	1		*FRONT GRILLE PANEL NO.4.2	Cut	187.74 FL	*187.74 FL
18	1		*FRONT GRILLE PANEL NO.4.3	Cut	187.74 FL	*187.74 FL
19	1		*FRONT PANEL	Cracked	1,081.64 FL	*1,081.64 FL
20	1		*FRONT WIPER PANEL	Repair	285.74 FL	*- FL
21	1		*FRONT WIPER PANEL REINFORCEMENT	Not Necessary	674.10 FL	*- FL
22	1		*FRONT CORNER PANEL RH	Cracked	1,103.34 FL	*1,103.34 FL
23	3		*FRONT WIPER ARM	Serviceable	619.74 FL	*- FL
24	3		*FRONT WIPER BLADE	Not Necessary	285.60 FL	*- FL
25	1		*FRONT WIPER LINK NO.1	Not Necessary	286.02 FL	*- FL
26	1		*FRONT WIPER LINK NO.2	Not Necessary	372.68 FL	*- FL
27	1		*FRONT WIPER MOTOR	Not Necessary	1,203.16 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	12,118.94	7,779.12
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,211.89	777.91
Total Parts (\$\$)	10,907.05	7,001.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO KNOCK AND RENEW ALL AFFECTED PARTS	New	1,400.00	1,000.00
2	TO RUST PROOFING ON AFFECTED AREA	New	680.00	0.00
3	TO SPRAY & PAINTING ON AFFECTED AREA	New	1,200.00	800.00
Gross Labour Cost (\$)			3,280.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >