

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22007788/KVY3Q2**Date:** 14/09/2022**REFERENCE**

Insured/Claimant:	BIS MOTORING PTE LTD	Policy No:	SP2002451400
Date of Loss:	06/08/2022	Nature of Claim:	OD
		Claim No:	202222006025SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR460G	Engine No:	A2191579L8GX0009
Make & Model:	OPEL ASTRA ST, 1.6 D TURBO DIESEL (A)	Chassis No:	W0VBD8EG3K8058051
Reg. Date:	16/12/2019 (Man. Year: 2019)	Odometer:	133498 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$91,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	DURATURN 8 mm	Rear Left Side:	DURATURN 8 mm
Front Right Side:	DURATURN 8 mm	Rear Right Side:	DURATURN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,432.16	3,798.90	4,633.26	54.95
Miscellaneous Items	108.00	108.00	0.00	0.00
Labour	2,630.00	1,270.00	1,360.00	51.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,170.16	5,176.90	5,993.26	53.65
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	9,170.16	3,176.90	5,993.26	65.36
+ GST 7.00/7.00% (S\$)	641.92	222.38	419.54	65.36
Nett Amount (S\$)	9,812.08	3,399.28	6,412.80	65.36

INSPECTION

Date of Assignment:	09/09/2022	Present Location:	Munich Autocare Pte Ltd (HQ)
Date Inspected:	16/08/2022	Inspected At:	Munich Autocare Pte Ltd (HQ)
			60 Jalan Lam Huat, #07-43
			Singapore 737869
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	144	OPEL ASTRA ST 1.6 D TURBO DIESEL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR460G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	39054067	*FRONT BONNET	Repair	997.00 F	*- FL
2	1	39032149	*BONNET HINGLE LH	Repair	32.00 F	*- FL
3	1	39032150	*BONNET HINGLE RH	Repair	32.00 F	*- FL
4	1	39089229	*FRONT RADIATOR GRILLE	Serviceable	400.00 F	*- FL
5	1	13423641	*FRONT RADIATOR GRILLE MOULDING CHROME LH	Serviceable	166.00 F	*- FL
6	1	13423642	*FRONT RADIATOR GRILLE MOULDING CHROME RH	Serviceable	166.00 F	*- FL
7	1	39052728	*FRONT BUMPER	Bent	1,256.00 F	*1,256.00 FL
8	1	39089220	*FRONT BUMPER LOWER GRILLE	Serviceable	138.00 F	*- FL
9	1	13447589	*FRONT PARKING SENSOR	Serviceable	80.00 F	*- FL
10	1	39150203	*FRONT HARDNESS WIRE	Torn	323.00 F	*323.00 FL
11	1	39081894	*FRONT HEADLAMP LH	Broken	609.00 F	*609.00 FL
12	1	39058200	*FRONT HEADLAMP LOWER BRACKET LH	Cracked	50.00 F	*50.00 FL
13	1	39086895	*FRONT HEADLAMP SIDE RENTAINER LH - UPP	Cracked	24.00 F	*24.00 FL
14	1	39098907	*FRONT BUMPER FOD LAMP LH	Broken	270.00 F	*270.00 FL
15	1	13481997	*FRONT BUMPER FOGLAMP COVER LH	Dented	165.00 F	*165.00 FL
16	1	39086922	*FRONT EMBLEM LOGO	Serviceable	109.00 F	*- FL
17	1	13423599	*FRONT BUMPER TOW COVER	Serviceable	48.00 F	*- FL
18	1	39089202	*FRONT BUMPER LOWER LIP LH	Serviceable	162.00 F	*- FL
19	1	39089203	*FRONT BUMPER LOWER LIP RH	Serviceable	162.00 F	*- FL
20	1	39058200	*FRONT BUMPER SIDE RETAINER LH - GUIDE	Cracked	50.00 F	*50.00 FL
21	1	13488987	*FRONT BUMPER HEADLAMP BRACKET LH	Serviceable	232.00 F	*- FL
22	1	39089229	*FRONT GRILLE FRAME	Serviceable	400.00 F	*- FL
23	1	39132771	*FRONT GRILLE BASE	Serviceable	124.00 F	*- FL
24	1	13423641	*FRONT GRILLE CHROME MOULDING LH	Serviceable	198.00 F	*- FL
25	1	39011390	*FRONT FENDER LH	Bent	442.00 F	*442.00 FL
26	1	13412038	*FRONT FENDER BRACKET LH	Repair	66.00 F	*- FL
27	1	39052081	*FRONT FENDER BRACKET LH	Repair	5.00 F	*- FL
28	1	39052083	*FRONT FENDER BRACKET LH	Repair	19.00 F	*- FL
29	1		*FRONT FENDER INNERSHIELD LH	Torn	96.00 F	*96.00 FL
30	1	39024544	*TYRE RIM 16	Dented	276.00 F	*276.00 FL
31	1	39155356	*WIPER WASHING TANK	Dented	91.00 F	*91.00 FL
Supplementary #1						
32	1	39158021	*DAYTIME CONTROL UNIT	Dented	455.20 F	*569.00 FL
33	1	39086891	*BRACKET BUMPER SIDE LH	Serviceable	22.40 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,665.60	4,221.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	422.10
+ Margin on L,N Items 10.00/0.00% (\$\$)	766.56	0.00
Total Parts (\$\$)	8,432.16	3,798.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BUMPER CLIP (NECESSARY)	49.00	49.00
2	1	FENDER CLIP (NECESSARY)	49.00	49.00
3	1	FENDER INNERSHIELD CLIP (NECESSARY)	10.00	10.00
Sub Total (\$\$)			108.00	108.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE,REFIX & REPAIR FRONT BUMPER, FRONT BONNET, FRONT FENDER, FRONT PASSENGER DOOR LH AND ALL THE EFFECTED AREAS.	New	1,000.00	500.00
2	TO REMOVE & REFIX FRONT PARKING SENSOR	New	80.00	50.00
3	TO CHECK FRONT WIRING HARDNESS FOR PROPER FUNCTION INCLUDING ADJUST HEADLAMP FOCUS	New	120.00	60.00
4	WHEEL ALIGNMENT	New	80.00	60.00
5	RESPRAY & PUTTY FRONT ACCIDENT POTION, FRONT BUMPER, FRONT FENDER, FRONT BONNET , FRONT PASSENGER DOOR LH, AND ALL THE EFFECTED AREAS.	New	1,000.00	600.00
Supplementary #1				
Labour Items				
6	TO REMOVE & REFIX, REPAIR, KNOCKING WELDING FRONT SUPPORT PANEL, CHASSIS LH & RH & DAMAGED AREAS	New	350.00	0.00
Gross Labour Cost (\$\$)			2,630.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >