



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. Q 69M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER ASSY	NOT NECESSARY	4,901.20	-
1	FRONT BUMPER LOWER GRILLE COMPLETE ASSY	NOT NECESSARY	1,889.60	-
1	FRONT BUMPER INNER SUPPORT	NOT NECESSARY	284.10	-
1	FRONT BUMPER RIGHT OUTER CHROME GARNISH	NOT NECESSARY	1,609.10	-
1	FRONT BUMPER RIGHT FOG LAMP	NOT NECESSARY	551.10	-
1	FRONT BUMPER RIGHT FOG LAMP OUTER GARNISH	NOT NECESSARY	660.50	-
1	FRONT BUMPER RIGHT BRACKET	NOT NECESSARY	128.10	-
1	FRONT BUMPER RIGHT RETAINER	NOT NECESSARY	155.50	-
1	FRONT RIGHT LED LAMP	NOT NECESSARY	652.50	-
1	FRONT RIGHT LED LAMP GRILLE GARNISH	NOT NECESSARY	880.80	-
1	FRONT BONNET ASSY	TO REPAIR SEE LABOUR	2,610.50	-
1	FRONT BONNET CHROME MOULDING	CUT	359.40	359.40
1	FRONT GRILLE COMPLETE ASSY	NOT NECESSARY	1,655.50	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	250.50	-
1	FRONT RIGHT HEADLAMP WITH MODULE COMPLETE ASSY	CRACKED	6,805.20	4,100.10
1	FRONT RIGHT HEADLAMP OUTER GARNISH	NOT NECESSARY	445.10	-
1	FRONT RIGHT HEADLAMP UPPER LID	CRACKED	185.50	185.50
1	FRONT RIGHT HEADLAMP LOWER LID	NOT NECESSARY	175.80	-
1	FRONT RIGHT FENDER	NOT NECESSARY	2,255.10	-
1	FRONT RIGHT FENDER INNER COWLING	NOT NECESSARY	380.20	-
	LESS 25% DISCOUNT		-6,708.83	-1,161.25
			20,126.47	3,483.75
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
6	FRONT GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
4	FRONT RIGHT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	30.00	-
10	FRONT BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
2	FRONT RIGHT PARKING SENSOR (SN)	NOT NECESSARY	850.00	-
			1,020.00	-

Report Ref No. CS/SMO22007790/Uvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET ASSY.		1,200.00	300.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION.		1,200.00	250.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	20.00
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA.	NOT NECESSARY	140.00	-
	TO SYNCHRONISE THE FRONT PARKING SENSOR AND CHECK FOR FUNCTION.	NOT NECESSARY	80.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			2,850.00	570.00
	GRAND TOTAL		23,996.47	4,053.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/SMO22007790/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.