

Submit to ins

not Authorized
 16/8/22
 2/5 \$3200/
 3 days

Q69M Toyota Vellfire

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy ^ ^	\$ 4,901.20 X
2	1	Front bumper lower grille complete assy ^ ^	\$ 1,889.60 X
3	1	Front bumper inner support ^ ^	\$ 284.10 X
4	1	Front bumper right outer chrome garnish ^ ^	\$ 1,609.10 X
5	1	Front bumper right fog lamp ^ ^	\$ 551.10 X
6	1	Front bumper right fog lamp outer garnish ^ ^	\$ 660.50 X
7	1	Front bumper right bracket ^ ^	\$ 128.10 X
8	1	Front bumper right retainer ^ ^	\$ 155.50 X
9	1	Front right LED lamp ^ ^	\$ 652.50 X
10	1	Front right LED lamp grille garnish ^ ^	\$ 880.80 X
11	1	Front bonnet assy R	\$ 2,610.50 X
12	1	Front bonnet chrome moulding cut	\$ 359.40 /
13	1	Front grille complete assy ^ ^	\$ 1,655.50 X
14	1	Front grille emblem ^ ^	\$ 250.50 X
15	1	Front right headlamp with module complete assy C/R	\$ 6,805.20 / 4100.10
16	1	Front right headlamp outer garnish ^ ^	\$ 445.10 X
17	1	Front right headlamp upper lid C/R	\$ 185.50 /
18	1	Front right headlamp lower lid ^ ^	\$ 175.80 X
19	1	Front right fender ^ ^	\$ 2,255.10 X
20	1	Front right fender inner cowlings ^ ^	\$ 380.20 X
			\$ 26,835.30
less 25%			\$ 6,708.83
			\$ 20,126.48

Special Nett Items

1	10	Front bumper clips ^ ^	\$ 60.00 X
2	6	Front grille clips ^ ^	\$ 40.00 X
3	4	Front right fender inner cowlings clips ^ ^	\$ 30.00 X
4	10	Front bumper lower grille clips ^ ^	\$ 40.00 X
5	2	Front right parking sensor ^ ^	\$ 850.00 X
			\$ 1,020.00

Total parts

\$ 21,146.48

Q69M Toyota Vellfire

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,200.00	300
2	To putty and spray painting front right portion.	\$ 1,200.00	250
3	To check wiring and focus front headlamp.	\$ 50.00	20
4	To remove and install front bonnet lock mechanism.	\$ 80.00	X
5	To apply anti rust proofing to front right affected area.	\$ 140.00	X
6	To synchronise the front parking sensor and check for function.	\$ 80.00	X
7	Towing service.	\$ 100.00	X
Total labour :		\$ 2,850.00	

Total parts : \$ 21,146.48

Total labour : \$ 2,850.00

Total repair cost : \$ 23,996.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4645
252
3483.75
570
4053.75
3243