

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22007791/KVY3Q2**Date:** 28/04/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SNC819Z **Insured Vehicle No :** SML1220H

Date of Loss: 30/07/2022 Nature of Claim: TP Claim No: DMCF2200158H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC819Z**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 2ZR2M74527

Reg. Date: 28/09/2021 (Man. Year: 2021) Chassis No: ZWR800504928

Colour: Metallic Silver Odometer: 0 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Davanti 6 mm Rear Left Side: Goodyear 8 mm

Front Right Side: Davanti 6 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,497.95	17,341.05	3,156.90	15.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,940.00	3,780.00	1,160.00	23.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,437.95	21,121.05	4,316.90	16.97
+ GST 8.00/8.00% (S\$)	2,035.04	1,689.68	345.36	16.97
Nett Amount (S\$)	27,472.99	22,810.73	4,662.26	16.97

INSPECTION

Date of Assignment: 16/08/2022

Date Inspected: 17/08/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Apr 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC819Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Buckled	926.30 FL	*926.30 FL
2	1		*FRT BONNET LOCK	Repair	158.70 FL	*- FL
3	1		*FRT BONNET MOULDING	Dented	380.50 FL	*380.50 FL
4	1		*FRT BONNET INSULATOR	Serviceable	310.50 FL	*- FL
5	1		*FRT BONNET LH HINGE	Distorted	105.60 FL	*105.60 FL
6	1		*FRT BONNET RH HINGE	Repair	105.60 FL	*- FL
7	1		*FRT HEADLAMP LH	Mtg Cracked	3,606.30 FL	*3,606.30 FL
8	1		*FRT HEADLAMP RH	Mtg Cracked	3,606.30 FL	*3,606.30 FL
9	1		*FRT BUMPER	Buckled	580.50 FL	*580.50 FL
10	1		*FRT LH BUMPER RETAINER	Distorted	105.60 FL	*105.60 FL
11	1		*FRT RH BUMPER RETAINER	Dented	105.60 FL	*105.60 FL
12	1		*FRT RADIATOR GRILLE ASSEMBLY	Cracked	624.90 FL	*624.90 FL
13	1		*FRT BUMPER LOWER GRILLE	Distorted	605.50 FL	*605.50 FL
14	1		*FRT SUPPORT PANEL ASSEMBLY	Repair	869.10 FL	*- FL
15	1		*FRT REINFORCEMENT BAR	Bent	350.20 FL	*350.20 FL
16	1		*FRT REINFORCEMENT SPONGE	Cracked	210.70 FL	*210.70 FL
17	1		*CONDENSOR	Bent	1,080.50 FL	*1,080.50 FL
18	1		*RADIATOR	Bent	1,190.00 FL	*1,190.00 FL
19	1		*FAN COWLING	Serviceable	210.30 FL	*- FL
20	1		*FRT BRACE PANEL	Repair	140.80 FL	*- FL
21	1		*FRT LH AIRGUIDE	Serviceable	105.60 FL	*- FL
22	1		*FRT RH AIRGUIDE	Serviceable	105.60 FL	*- FL
23	1		*FRT COOLANT SPARE TANK	Serviceable	129.70 FL	*- FL
24	1		*FRT LICENCE PLATE	Serviceable	45.00 FS	*- FS
25	1		*FRT LH FENDER	Buckled	688.50 FL	*688.50 FL
26	1		*FRT LH FENDER INNER COWLING	Serviceable	210.70 FL	*- FL
27	1		*REAR TAILGATE	Bent	1,919.30 FL	*1,919.30 FL
28	1		*REAR TAILGATE WEATHERSTRIP	Dented / Distorted	280.60 FL	*280.60 FL
29	1		*REAR TAILGATE CHROME MOULDING	Mtg Cracked	780.30 FL	*780.30 FL
30	1		*REAR TAILGATE EMBLEM	Serviceable	101.50 FL	*- FL
31	1		*REAR TAILGATE LOCK	Jammed	505.60 FL	*505.60 FL
32	1		*REAR BUMPER	Bent	680.60 FL	*680.60 FL
33	1		*REAR BUMPER LH REFLECTOR	Serviceable	65.40 FL	*- FL
34	1		*REAR BUMPER RH REFLECTOR	Cracked	65.40 FL	*65.40 FL
35	1		*REAR LH CORNER PANEL	Serviceable	210.30 FL	*- FL
36	1		*REAR RH CORNER PANEL	Buckled	210.30 FL	*210.30 FL
37	1		*REAR PARKING SENSOR	Cracked	380.60 FL	*380.60 FL
38	1		*REAR END PANEL OUTER	Bent	580.60 FL	*580.60 FL
39	1		*REAR END PANEL GARNISH	Dented	210.40 FL	*210.40 FL
40	1		*REAR SPARE TYRE TANK TOP BOARD	Deformed	645.60 FL	*645.60 FL
41	1		*REAR SPARE TYRE TANK	Serviceable	639.70 FL	*- FL
42	1		*REAR RH FENDER INNER TRIM	Buckled	680.30 FL	*680.30 FL
43	1		*REAR LH FENDER INNER TRIM	Serviceable	680.30 FL	*- FL
44	1		*REAR BUMPER RH RETAINER	Distorted	105.40 FL	*105.40 FL
45	1		*REAR BUMPER LH RETAINER	Serviceable	105.40 FL	*- FL
46	1		*L TOYOTA COOLANT	Necessary	86.20 FL	*86.20 FL

Report was unsubmitted during this print-out.

4/28/23, 9:50 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BATTERY COOLER	Bent	1,008.30 FL	*1,008.30 FL
48	1		*TAILGATE INNER TRIM	Buckled	617.60 FL	*617.60 FL
49	1		*SPARE TYRE JACK BRACKET	Bent	119.00 FL	*119.00 FL
50	1		*REAR SENSOR BRACKET	Distorted	60.30 FL	*60.30 FL
51	1		*TAILGATE HANDLE	Dented	18.00 FL	*18.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					27,315.60	23,121.40
- List Item Discount on L Items 25.00/25.00% (\$\$)					6,817.65	5,780.35
Total Parts (\$\$)					20,497.95	17,341.05
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA ,TO REMOVE & REFIT FRONT AFFECTED DAMAGE PARTS	New	800.00	600.00
2	TO PUTTY & RESPRAY ON FRONT AFFECTED AREA	New	1,200.00	800.00
3	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA ,TO REMOVE & REFIT REAR AFFECTED DAMAGE PARTS	New	1,400.00	1,100.00
4	TO PUTTY & RESPRAY ON REAR AFFECTED AREA	New	1,200.00	1,000.00
5	TO REMOVE & REFIT TAILGATE GLASS	New	120.00	120.00
6	TO REMOVE & REFIT REAR INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	120.00	120.00
7	TO CHECK WIRING	New	100.00	40.00
Gross Labour Cost (\$\$)			4,940.00	3,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >