

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122007792/DNY3M4**Date:** 17/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHA7995H**Insured Vehicle No :** XE1932T

Date of Loss: 13/08/2022

Nature of Claim: TP

Claim No: CDMCG22001660

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA7995H**

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)

Engine No: G4LEKU409554

Reg. Date: 30/09/2020 (Man. Year: 2019)

Chassis No: KMHC851CVLU190091

Colour: Blue

Odometer: 0 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,030.52	10,302.00	9,728.52	48.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	1,390.00	3,610.00	72.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,030.52	11,692.00	13,338.52	53.29
+ GST 8.00/8.00% (S\$)	2,002.44	935.36	1,067.08	53.29
Nett Amount (S\$)	27,032.96	12,627.36	14,405.60	53.29

INSPECTION

Date of Assignment: 16/08/2022

Date Inspected: 16/08/2022 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate

Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2023)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7995H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	237.40 FL	*- FL
3	1		*BONNET MOULDING	Not Necessary	41.40 FL	*- FL
4	1		*BONNET LOCK	Bent	127.30 FL	*127.30 FL
5	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
7	1		*BONNET CABLE	Not Necessary	135.60 FL	*- FL
8	1		*RADIATOR GRILLE NEW MODEL	Broken	1,568.60 FL	*1,568.60 FL
9	1		*FLAP ASSY ACTIVE AIR UPPER, (RH)	Not Necessary	824.60 FL	*- FL
10	1		*SPEAKER ASSY-VESS	Not Necessary	554.40 FL	*- FL
11	1		*UNIT ASSY-SMART CRU (RADAR SENSOR)	Not Necessary	3,061.40 FL	*- FL
12	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	188.00 FL	*- FL
13	1		*FRONT BUMPER COVER	Distorted	481.10 FL	*481.10 FL
14	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
15	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent/Dented	1,136.70 FL	*1,136.70 FL
17	1		*FRONT BUMPER REINFORCEMENT ABSORBER (RH)	Serviceable	186.50 FL	*- FL
18	1		*FRONT BUMPER MOULDING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
19	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
20	1		*FRONT BUMPER BRACKET TOP (RH)	Broken	35.00 FL	*35.00 FL
21	1		*FRONT BUMPER BRACKET (RH)	Broken	28.00 FL	*28.00 FL
22	1		*FRONT BUMPER RETAINER MOUNTING (RH)	Not Necessary	65.30 FL	*- FL
23	1		*FRONT BUMPER CLIPS 10 PCS	Necessary	25.00 FL	*25.00 FL
24	1		*FRONT BUMPER GRILLE (RH)	Cut	186.90 FL	*186.90 FL
25	1		*FRONT BUMPER AIR DUCT (RH)	Not Necessary	153.80 FL	*- FL
26	1		*DAY LIGHT , RH	Mtg Broken	642.50 FL	*642.50 FL
27	1		*HEADLAMP SUPPORT PANEL ASSY	Mtg Cracked	1,139.30 FL	*1,139.30 FL
28	1		*HEADLAMP(RH)	Broken	3,987.30 FL	*2,110.30 FL
29	1		*HORN UNIT (RH)	Not Necessary	72.80 FL	*- FL
30	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
31	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
32	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,459.60 FL	*- FL
33	1		*RADIATOR AIR GUARD (RH)	Not Necessary	76.40 FL	*- FL
34	1		*RADIATOR AIR GUARD, UPR (RH)	Not Necessary	127.50 FL	*- FL
35	1		*FRT PILLAR UPPER COVER - OUTER RH	Dislodged	89.60 FL	*89.60 FL
36	1		*FRONT FENDER(RH)	Dented	490.70 FL	*490.70 FL
37	1		*FRONT FENDER APRON PANEL SIDE SUPPORT (RH)	Not Necessary	238.80 FL	*- FL
38	1		*FRONT FENDER APRON PANEL (RH)	Not Necessary	756.20 FL	*- FL
39	1		*FRONT FENDER APRON PANEL UPPER (RH)	Not Necessary	329.00 FL	*- FL
40	1		*FRONT FENDER SHIELD (RH)	Not Necessary	164.70 FL	*- FL
41	1		*AIRCON CONDENSER	Not Necessary	663.60 FL	*- FL
42	1		*WIPER CONTAINER ASSY	Deformed	385.40 FL	*385.40 FL
43	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
44	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
45	1		*COOLANT	Not Necessary	45.00 FS	*- FS
46	1		*EMBLEM-BLUE DRIVE (RH)	Necessary	26.60 F	*26.60 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$)					25,006.50	12,877.50
- List Item Discount on L Items 20.00/20.00% (\$)					4,975.98	2,570.18
- Nett Item Discount on N Items 0.00/20.00% (\$)					0.00	5.32
Total Parts (\$)					20,030.52	10,302.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING CHARGE	New	1,600.00	600.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	30.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX RADIATOR	New	90.00	50.00
7	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
9	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR	New	550.00	0.00
Gross Labour Cost (\$\$)			5,000.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >