



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3064E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	920.00	-
1	HEADLAMP LH	CRACKED	2,637.60	2,637.60
1	FRONT BUMPER COVER	DEFORMED	586.18	586.18
1	FRONT BUMPER SIDE BRACKET LH	DEFORMED	90.75	90.75
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-1,064.13	-834.13
			3,192.40	2,502.40
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADVERTISEMENT LOGO LH (SN)	NOT NECESSARY	100.00	-
			100.00	-
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	CHECK ALL LIGHTING.		50.00	30.00
			1,050.00	630.00
GRAND TOTAL			4,342.40	3,132.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,500.00

Report Ref No. NS/INC22007801/Tcm4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.