

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22007802/UQY3M4**Date:** 31/08/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961125		
Claimant Vehicle No :	SMM5556H	Insured Vehicle No :	SLN8014S		
Date of Loss:	12/08/2022	Nature of Claim:	TP	Claim No:	282038

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM5556H		
Make & Model:	HONDA FREED HYBRID, 1.5 7-SEATER G (A)	Engine No:	LEB5641114
Reg. Date:	03/07/2019 (Man. Year: 2019)	Chassis No:	GB71100191
Colour:	Grey	Odometer:	289168 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Triangle 7 mm	Rear Left Side:	Triangle 7 mm
Front Right Side:	Triangle 7 mm	Rear Right Side:	Triangle 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,094.80	3,175.92	7,918.88	71.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,890.00	1,620.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,604.80	5,065.92	9,538.88	65.31
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	14,604.80	4,000.00	10,604.80	72.61

INSPECTION

Date of Assignment:	17/08/2022	
Date Inspected:	16/08/2022 Inspected At:	2ND Auto Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre Singapore 417808
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2022)

Parts: M1-MPV HONDA FREED HYBRID 1.5 7-SEATER G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM5556H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER ASSY	Deformed	1,207.90 FL	*841.10 FL
2	2	*REAR BUMPER BRACKET	No such part	125.60 FL	*- FL
3	1	*REAR BUMPER RETAINER (2PCS)	N/s Bent (1Piece Only)	126.80 FL	*45.50 FL
4	1	*REAR BUMPER TOW COVER	Not Necessary	66.30 FL	*- FL
5	2	*REAR BUMPER REFLECTOR	Not Necessary	303.60 FL	*- FL
6	1	*REAR TAILGATE ASSY	Badly Dented	1,857.20 FL	*1,245.30 FL
7	1	*REAR TAILGATE INNER TRIM BOARD	Not Necessary	232.80 FL	*- FL
8	1	*REAR TAILGATE INNER TRIM BOARD INNER HANDLE	Not Necessary	86.20 FL	*- FL
9	1	*REAR TAILGATE WEATHERSTRIP	Twisted	288.60 FL	*245.10 FL
10	1	*REAR TAILGATE LOCK MECHANISM	Bent	188.20 FL	*188.20 FL
11	1	*REAR TAILGATE LOCK CATCH	Not Necessary	86.70 FL	*- FL
12	1	*REAR TAILGATE LOCK SWITCH	Not Necessary	215.30 FL	*- FL
13	1	*REAR TAILGATE INNER HANDLE	Not Necessary	88.60 FL	*- FL
14	1	*REAR TAILGATE OUTER CHROME GARNISH	Not Necessary	240.20 FL	*- FL
15	1	*REAR TAILGATE CENTER LOGO	Necessary	68.80 FL	*38.00 FL
16	1	*REAR TAILGATE FREED EMBLEM	Necessary	66.50 FL	*66.50 FL
17	1	*REAR TAILGATE HYBRID EMBLEM	Necessary	66.50 FL	*66.50 FL
18	2	*REAR TAILGATE HINGES	Not Necessary	161.10 FL	*- FL
19	2	*REAR TAILGATE DAMPER	Not Necessary	271.60 FL	*- FL
20	1	*REAR TAILGATE WIPER MOTOR	Not Necessary	579.40 FL	*- FL
21	1	*REAR TAILGATE WIPER BLADE ASSY	Not Necessary	163.30 FL	*- FL
22	2	*REAR TAILGATE NO PLATE LAMP	Not Necessary	123.50 FL	*- FL
23	1	*REAR END PANEL	Dented/Bent	841.70 FL	*541.00 FL
24	1	*REAR END PANEL TOP GARNISH	Twisted	129.90 FL	*129.90 FL
25	1	*REAR WINDSCREEN GLASS MOULDING	Necessary	188.90 FL	*112.80 FL
26	1	*REAR TAILGATE LEFT TAILLAMP	Not Necessary	440.20 FL	*- FL
27	1	*REAR TAILGATE RIGHT TAILLAMP	Not Necessary	440.20 FL	*- FL
28	1	*REAR LEFT TAILLAMP	Not Necessary	605.10 FL	*- FL
29	1	*REAR RIGHT TAILLAMP	Not Necessary	605.10 FL	*- FL
30	1	*REAR LEFT FENDER	Not Necessary	1,272.50 FL	*- FL
31	1	*REAR LEFT FENDER INNER GARNISH	Not Necessary	435.20 FL	*- FL
32	1	*REAR LEFT FENDER INNER COWLING	Not Necessary	218.90 FL	*- FL
33	1	*REAR LEFT AIR DUCT VENTILATOR	Not Necessary	88.60 FL	*- FL
34	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
35	4	*REAR TAILGATE OUTER CHROME GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
36	8	*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
37	1	*REAR END PANEL SEALANT	Necessary	140.00 FS	*50.00 FS
38	4	*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
39	1	*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
40	1	*REAR WINDSCREEN GLASS RUBBER SEAL	Necessary	100.00 FS	*30.00 FS
41	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
42	1	*REAR NO PLATE	Not Necessary	100.00 FS	*- FS
43	10	*REAR LEFT FENDER INNER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
44	6	*REAR LEFT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
45	1	*REAR LEFT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

8/31/22, 2:19 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR LEFT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
47	1		*REAR VIEW CAMERA	Not Necessary	450.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	13,471.00
					3,879.90	
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,376.20
						703.98
					Total Parts (\$\$)	11,094.80
						3,175.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	900.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	0.00
6	TO REMOVE AND INSTALL REAR SEAT, INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	180.00	80.00
7	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	60.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
10	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	0.00
11	TO REMOVE AND INSTALL REAR LEFT QUARTER GLASS	New	80.00	0.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$)			3,510.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >