

INC

ASSIGNMENT

[illegible]

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

Page 1 of 2

DATE: 12.08.2022 (FRONT)

INSURANCE: NTUC

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHA2673U

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Radiator Grille	1		\$ 1,409.10
	Front Bumper Cover	1		\$ 481.10
	Front Bumper Moulding Centre Upper	1		\$ 368.50
	Front Bumper Grille LH / RH	2	\$ 93.45	\$ 186.90
	Front Bumper Towing Cover	1		\$ 29.00
	Front Bumper Lower Moulding	1		\$ 368.50
	Front Bumper Lower Stiffner	1		\$ 285.10
	Front Bumper Lip	1		\$ 35.10
	Front Bumper Bracket Top (LH/RH)	2	\$ 35.00	\$ 70.00
	Front Bumper Bracket (LH/RH)	2	\$ 28.00	\$ 56.00
	Front Bumper Clips 10 pcs	10	\$ 2.20	\$ 22.00
	Front Bumper Lower Grille	1		\$ 365.30
	Headlamp Support Panel Assy	1		\$ 949.30
	Headlamp LH / RH	2	\$ 2,110.30	\$ 4,220.60
	Day Light ,LH / RH	2	\$ 642.50	\$ 1,285.00
	Front Fender Shield LH	1		\$ 164.70
	Flap Assy Active Air Upper LH	1		\$ 824.60
	Actuator Active Air LH	1		\$ 257.10
	Front Fender RH	1		\$ 588.80
	Bonnet	1		\$ 2,253.80
	Radiator Inverter	1		\$ 884.80
	Radiator	1		\$ 710.50
	Radiator Fan Motor	1		\$ 576.00
	Radiator Fan	1		\$ 375.10
	Air Con Condenser	1		\$ 663.60
	SUB TOTAL			\$ 17,430.50
	LESS 20%			\$ 3,486.10
	DISCOUNTED TOTAL			\$ 13,944.40
	Front No. Plate With Trim Cover	1		\$ 55.00
	LESS 10%			\$ 5.50
	NETT TOTAL			\$ 49.50
	SPARE PARTS TOTAL			\$ 13,993.90
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 40.00
	Tuff Kote			\$ 40.00
	R/I Air Con Condenser Etc			\$ 150.00
	Towing Fee			Nil
	TOTAL LABOUR			\$ 2,630.00
	ESTIMATE TOTAL			\$ 16,623.90

Tanphu 97475749
 Wp: 12/8/2022 430pm
 2/3 Repair after repair
 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

700
 250
 30
 30
 100
 X

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK -

DATE: 12.08.2022

(REAR)

Page 2 of 2

MODEL: Hyundai Ioniq

INSURANCE: NTUC - (45)

VEHICLE NO.: SHA2673U

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH/RH	2	\$ 138.10	\$ 276.20
	Rear Bumper Side Brackets LH/RH	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding Assy	1		\$ 451.25
	Rear Bumper Lower Centre Moulding Assy	1		\$ 155.00
	Rear Bumper Under Cover	1		\$ 225.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp RH	1		\$ 41.45
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Smart Key Antenna	1		\$ 40.50
	Rear Foglamp	1		\$ 201.50
	SUB TOTAL			\$ 2,477.50
	LESS 20%			\$ 495.50
	DISCOUNTED TOTAL			\$ 1,982.00
	Reverse Sensors	1		\$ 180.00
	Rear No. Plate With Trim Cover	1		\$ 55.00
	S/NETT SUB			\$ 235.00
	LESS 10%			\$ 23.50
	S/NETT TOTAL			\$ 211.50
	Rear Bumper Mat	1		\$ 50.00
	Rear Fender Adv. Sticker RH / LH	2	\$ 100.00	\$ 200.00
	SPARE PARTS TOTAL			\$ 2,443.50
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 3,263.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjun E. Ikhant.com

Date/Time: 12.08.2022 10:17

Page : 1

1: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4525128

JC No: 805526302

OMER

S COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P) (O)

OUNT CARD NO.

REGN NO.:

SHA2673U

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

11.08.2022 19:00

DATE/TIME IN

YR OF MANU.

01.02.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU133815

COMPLETION DATE/TIME:


JOB DESCRIPTION

ident Date: 11.08.2022

URE: 3P 11.08.2022

O LABOR CODE
010 PB

DESCRIPTION
PANEL BEATING-SHA2673U-TP



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHA2673U

LIMITS

Vehicle No.:

SHA2673U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition


1. Date: <u>11/8/22</u> Time Received: <u>1900</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☐ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
2. ☐ New ☐ SPARK Kakis Name of Customer : Contact No. : <u>90112242</u> Vehicle No. : <u>✓ S4A 2673-U</u> Make / Model / Colour : <u>1Q</u> Email :		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>BT Timah Rd</u>		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____			

10. Odometer Reading : _____

Fuel Level :

F	1/4	1/2	3/4	E
---	-----	-----	-----	---

11. Radio / CD Player
☐ OK
☐ Faulty
☐ Not tested



: Cracked X : Dented
/ : Scatched O : Missing

Signature of Customer

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ GAO ☐ OTHERS

Name of Driver : 1606

Vehicle No. : TR7717R

Time Dispatch : 11/8/22

Time of Arrival : 19.30

Time Completed : _____

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

WORKSHOP COPY