NS/IN	IC22007806/Tqc	2 - 42	* 1
A.S.S. RECBY: TOUM	SSIGNMENT		
-		3875 Yr Regn: 22.9, NOV	
From: Date:			
Estimated lost:		Van   Lorry (Taxi ) Prime Mover !	
OD ITP I IS ITP RES / OD RES / EVA / INV / MV	Truck / Trailer or	der Coma ca 1580	
To InspeciVehicle No:	- 101		20
at Workship m/s	Colour 93th		
of	Sp.Reading	T/Radio: Insured / Std / NI / NA	
Insured:	Eng/No:	0.1/1/00.0/10	
Policy No.	C/No: King	4C85/CV1.4188049	_
Claims No	Gen. Cond: Good / Fair / Pe		
Sum Insued: Excess:	Steering: Inorder / Jammer	the Commence of the Commence o	
(Client'sRecord)	Brake: Inorder / Jamme	d / Leakad / Burnt or	_
Make of Veh:	Modi: Nit / S/Rim / ST		_
	Tyre Size: F:	195/65RIS	
(Policy Condition)	R:	1 -	_
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY	I-FS   LIZA   MIC   OHTSU   PIR   SUMI	to
repair at the time of inspection.	TOYO / YOKO or	werfull.	_
Bal. or Market Value:	<u>Front</u>	Rear	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal.	mm R/Bal. mm	1
GIA / PR Seen: Consistent? : Yes or No	L/Bal.	mm . L/Bal mn	n
Est. Repairs: 2 days Res.: Yes or No	D.O.A.	D.O.I. 12/8/22	
Lum Sum: % 3 Val.: Yes or No	Survey held at	worfet logar.	
CA / REV / REP. / 24 HRS		Rear   O/S   N/S U/G Rooftop or	
Vehicle:	IN I OUT	RV + MS	OD.
Date:Person Contacted:	The U/C / Chassis	frame / Body Structure affected due to collisi	
Date /Time   Action / Instruction   Taufikh finalised LS \$3550, 2	) days (Pod \$1770.52 f	220/	1.
Taulikii iiilalised LS \$3330, 2	2 days. (Red \$1779.52,	55 70)	34
	1		
	•		
			-
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	2	
: Final Report	Resurvey No. of Tri	p: 1 Survey Fee:	
Date/Time, File Return to?	▼ Provide State (1997)	Transportation:	
	Add Fee: : Site Insp	)S+RS,SI	
	: Interview	) Photos	~_;
Reperier TP	: Tech. Invs	\$) Others	
Lump Sum (1.8.1.17) 3550	:VVestiend	\$	
38 19		TOTAL	

## **COMFORT TRANSPORTATION PTE LTD**

## REPAIR ESTIMATE

Vehicle No.: SHC1387S

Make : HYUNDAI

Model : IONIQ(G3) Date: 12.08.2022

Insurance: NTUC

MVA: MS. LOKE YY

MPER COVER MPER CLIPS MPER SIDE BRACKET LH MPER CENTRE MOULDING UPPER AMP LH MPER SIDE MOULDING LH GHT LH NDER LH M - BLUE DRIVE LH HEEL HUB CAP LH  SUB TOTAL LESS 20% DISCOUNTED TOTAL		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	481.10 22.00 28.00 368.50 2,110.30 93.45 642.50 588.80 26.60 346.40 4,707.65 948.13 3,759.52
MPER SIDE BRACKET LH MPER CENTRE MOULDING UPPER AMP LH MPER SIDE MOULDING LH SHT LH NDER LH M - BLUE DRIVE LH HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$ \$ \$ \$ \$ \$ \$ \$	28.00 368.50 2,110.30 93.45 642.50 588.80 26.60 346.40 4,707.65 948.13
MPER CENTRE MOULDING UPPER  AMP LH  MPER SIDE MOULDING LH  GHT LH  NDER LH  M - BLUE DRIVE LH  HEEL HUB CAP LH  SUB TOTAL  LESS 20%		\$ \$ \$ \$ \$ \$ \$ \$	368.50 2,110.30 93.45 642.50 588.80 26.60 346.40 4,707.65 948.13
AMP LH MPER SIDE MOULDING LH SHT LH NDER LH M – BLUE DRIVE LH HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$ \$ \$ \$ \$ \$ \$	2,110.30 93.45 642.50 588.80 26.60 346.40 4,707.65 948.13
MPER SIDE MOULDING LH SHT LH NDER LH M – BLUE DRIVE LH HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$ \$ \$ \$	93.45 642.50 588.80 26.60 346.40 4,707.65 948.13
SHT LH NDER LH M – BLUE DRIVE LH HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$ \$ \$ \$ \$	642.50 588.80 26.60 346.40 4,707.65 948.13
NDER LH M – BLUE DRIVE LH HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$ \$ \$	588.80 26.60 346.40 4,707.65 948.13
M – BLUE DRIVE LH HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$ \$	26.60 346.40 4,707.65 948.13
HEEL HUB CAP LH SUB TOTAL LESS 20%		\$ \$	346.40 4,707.65 948.13
SUB TOTAL LESS 20%		\$	4,707.65 948.13
LESS 20%		\$	948.13
DISCOUNTED TOTAL		\$	3,759.52
	l .		
NDER ADVERTISEMENT LH		\$	100.00
		\$	100.00
Charge			
		1000	750.00
		1779	600.00
			60.00
	16	_	60.00
TOTAL LABOUR		\$	1,470.00
		\$	5,329.52
	PAINTING CHARGE OTE	PAINTING CHARGE OTE LIGHTING / WIRING TOTAL LABOUR	PAINTING CHARGE OTE LIGHTING / WIRING  TOTAL LABOUR  \$

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfin 9749549

up 1218122 C 4pn

up 1218122 C 4pn

up affer epen

fungthi C Whants un
2-3 dexs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date.



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701

Date/Time: 12.08.2022 15:43

SHC1387S

Page: 1

'eam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4525206

JC N905526307

MILEAGE

FUEL

USTOMER

R/MS COMFORT TRANSPORTATION PTE LTD

7010045 USTOMER NO.

ODRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

EL. (R) 65508755

HYUNDAI E.....F MODEL DATE/TIME IN IONIQ(G3) 11.08.2022 22:15

REGN NO.

MAKE:

YR OF MANU. 07.11.2019

Date

TARGET DATE

CHASSIS CODE

KMHC851CVLU188049

COMPLETION DATE/TIME:

SCOUNT CARD NO.

(P)

JOB DESCRIPTION


.ccident Date: 11.08.2022 ATURE: 3P 11.08.2022 v

sturned to Service Reception upon collection

/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:				
SERVICE ADVI	SOR			CUSTOMER'S SIGNATURE
wledgement Slip			Exit Pass	
No.: SHC1387S	YY		Vehicle No.: SHC1387S	
of Service Advisor		Signature/Date	Name of Service Advisor	Date

To be kept by Security Guard