

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8997K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LEFT FENDER SUB ASSY	BENT	1,111.93	1,111.93
1	FRONT FENDER HYBRID EMBLEM LH	NECESSARY	86.50	86.50
1	FRONT FENDER SHIELD LH	TORN	198.50	198.50
1	FRONT BUMPER COVER	TORN	586.18	586.18
1	FRONT BUMPER SIDE BRACKET LH	DEFORMED	82.30	82.30
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP LH	CRACKED	2,735.28	2,735.28
1	FRONT BUMPER SIDE RETAINER LH	CUT	77.00	77.00
1	FRT BUMPER SIDE GRILLE	CUT	85.10	85.10
1	FRT BUMPER SPONGE	NOT NECESSARY	78.80	-
1	FRT BUMPER TOW COVER LH	NOT NECESSARY	28.38	-
1	FRT WHEEL RIM LH	TO REPAIR SEE LABOUR	1,570.55	-
	LESS 25% DISCOUNT		-1,665.63	-1,246.20
			4,996.89	3,738.59
	SPECIAL NETT ITEMS			
1	FRT TYRE LH (SN)	NOT NECESSARY	216.00	-
			216.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT WHEEL RIM LH .		1,100.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	30.00
	CHECK ALL LIGHTING.		60.00	30.00
			1,820.00	1,085.00
	GRAND TOTAL		7,032.89	4,823.59





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		4,823.59
(CONFIRMED)		

Report Ref No. NS/INC22007807/Tncq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser