



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 1292G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR MUDGUARD O/S (NPA)	TO REPAIR SEE LABOUR	-	-
			-	-
	<u>NETT ITEMS</u>			
1	REAR BUMPER (N)	DEFORMED	722.90	667.20
1	REAR TAILLAMP O/S (N)	CRACKED	289.80	224.70
	LESS 10% DISCOUNT		-	-89.19
			1,012.70	802.71
	<u>LABOUR</u>			
	TO REMOVE, REPAIR, REPLACE & INSTALL REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR MUDGUARD O/S.		800.00	500.00
	TO R & R WIRING.		60.00	30.00
	TO PUTTY & SPRAY PAINTING.		600.00	450.00
			1,460.00	980.00
	GRAND TOTAL		2,472.70	1,782.71
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/FCI22007810/Tcy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.