



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22007810/Tcy3m4 Date: 16/03/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YM 9786S	Veh. Inspected	GBG 1292G
Policy No.	D-21098552MCVP	Coverage (\$)	0.00
Claim No.	D22002497MCVP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	16/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1MC2E26Z0007976	Colour	GREY
Odometer	159098 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/R15	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	12/08/2022	Inspection Date	17/08/2022
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	