

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007811/KPA3Q2
Date: 30/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070057637-02
Claimant Vehicle No :	SMQ7753X	Insured Vehicle No :	SFZ5246S
Date of Loss:	07/08/2022	Nature of Claim:	TP
		Claim No:	4142334146SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ7753X	Engine No:	2NR5405851
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3701194292
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	179810 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	4,071.25	3,049.05	1,022.20	25.11	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,180.00	1,410.00	770.00	35.32	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	6,251.25	4,459.05	1,792.20	28.67	
Approved Total (Overridden) (S\$)		3,550.00			
	(S\$)	6,251.25	3,550.00	2,701.25	43.21
+ GST 7.00/7.00% (S\$)	437.59	248.50	189.09	43.21	
Nett Amount (S\$)	6,688.84	3,798.50	2,890.34	43.21	
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00			
+ Doc/Search Fee (S\$)		2.00			
Nett Liability (S\$)		4,150.50			
Global Sum Settlement (S\$)		4,150.00			

INSPECTION

Date of Assignment:	16/08/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	16/08/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP LH	Serviceable	390.00 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	95.00 FL	*95.00 FL
3	1		*REAR BUMPER	Mtg Cracked	545.00 FL	*545.00 FL
4	1		*REAR BUMPER SIDE BRACKET LH	Distorted	155.00 FL	*155.00 FL
5	1		*REAR BUMPER SEAL LH	Serviceable	75.00 FL	*- FL
6	1		*REAR TAIL LAMP BRACKET LH	Serviceable	60.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR LH	Serviceable	98.00 FL	*- FL
8	1		*REAR FENDER LH	Bent	907.00 FL	*892.10 FL
9	1		*REAR RIM LH	Dented	1,891.00 FL	*1,623.10 FL
10	1		*REAR ABSORBER LH	Bent	150.00 FL	*150.00 FL
11	1		*REAR WHEEL BEARING HUB LH	Bent	849.00 FL	*485.20 FL
12	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
13	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
14	1		*REAR FENDER SHIELD CLIPS LH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,375.00	4,035.40
- List Item Discount on L Items 25.00/25.00% (\$)	1,303.75	986.35
Total Parts (\$)	4,071.25	3,049.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	600.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER REAR FENDER LH & ETC	New	600.00	400.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH & CUSHION UPHOLSTERY SET & ETC TO EFFECT REPLACE OF REAR FENDER LH	New	300.00	100.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC	New	150.00	120.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR RIM LH ,REAR ABSORBER LH,REAR WHEEL BEARING HUB LH & ETC	New	250.00	120.00
6	TO WHEEL ALIGNMENT & BALANCING	New	80.00	20.00
7	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$)			2,180.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >