

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122007812/RCY3E2

Date: 29/08/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SHF193A **Insured Vehicle No :** SLX4948X
Date of Loss: 10/08/2022 Nature of Claim: TP Claim No: CDMPG22001604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF193A**
Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR2F45541
Reg. Date: 26/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU903089435
Colour: Maroon Odometer: 193878 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm
Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,203.40	0.00	3,203.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,434.00	400.00	1,034.00	72.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,637.40	400.00	4,237.40	91.37

INSPECTION

Date of Assignment: 11/08/2022
Date Inspected: 11/08/2022 Inspected At: Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2022)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF193A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER REINFORCEMENT	Not Necessary	332.70 F	*- F
2	2		*PAD, RR BUMPER, RH & LH, 3	Not Necessary	22.00 F	*- F
3	2		*PAD, RR BUMPER, RH & LH, 2	Not Necessary	8.00 F	*- F
4	2		*PAD, RR BUMPER, RH & LH, 1	Not Necessary	8.00 F	*- F
5	3		*PAD, RR BUMPER, CTR	Not Necessary	33.00 F	*- F
6	2		*SEAL, RR BUMPER ARM, RH & LH	Not Necessary	22.60 F	*- F
7	2		*STOPPER, RR BUMPER, RH & LH	Not Necessary	4.50 F	*- F
8	1		*RETAINER, RR BUMPER, RH	Not Necessary	132.60 F	*- F
9	1		*SEAL, RR BUMPER, RH	Not Necessary	118.30 F	*- F
10	10		*CLIPS PIECE, FRT & RR BUMPER	Not Necessary	45.00 F	*- F
11	1		*GUARD, RR BUMPER, LOWER	Not Necessary	374.50 F	*- F
12	1		*REAR BUMPER REFLECTOR ASSY, REFLEX, RH	Not Necessary	39.00 F	*- F
13	2		*REAR BUMPER GROMMET SCREW	Not Necessary	4.40 F	*- F
14	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	175.10 F	*- F
15	1		*COVER, REAR FLOOR UNDER CENTER	Not Necessary	229.90 F	*- F
16	1		*LENS & BODY, REAR COMBINATION LAMP, RH	Not Necessary	339.60 F	*- F
17	1		*LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	Not Necessary	261.00 F	*- F
18	1		*LAMP ASSY, REAR, RH	Not Necessary	293.60 F	*- F
19	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
20	1		*ANTENNA, ELECTRICAL KEY	Not Necessary	72.00 F	*- F
21	1		*COVER, RR BUMPER ASSY	Repair	485.60 F	*- F
22	1		*COVER, GUARD RR BUMPER LOWER	Not Necessary	22.00 F	*- F

F=Franchise part.

Total Parts (\$\$) **3,203.40** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	378.00	200.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,434.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >