



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 8926P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LHS DOOR	DENTED	678.42	678.42
1	FRONT LHS DOOR INNER TRIM	BROKEN	265.85	265.85
1	FRONT LH DOOR WINDOW	BROKEN	99.35	99.35
1	FRONT LH DOOR WINDOW OUTER GRILLE	CUT	41.17	41.17
1	FRONT LH DOOR OUTER HANDLE	BROKEN	36.52	36.52
1	FRONT LH DOOR WINDOW REGULATOR	NOT NECESSARY	124.73	-
1	FRONT LH DOOR WINDOW MOTOR	NOT NECESSARY	220.56	-
1	SIDE MIRROR LH ASSY	BROKEN	148.10	148.10
1	SIDE MIRROR LH INNER COVER	MISSING	22.00	22.00
1	FRONT LH WHEEL MUDGUARD	BROKEN	42.31	42.31
1	FRONT LH DOOR INNER WINDOW RUN MOULDING	BENT	89.90	89.90
1	FRONT LH DOOR WINDOW RUN CHANNEL	CRUSHED	49.76	49.76
1	FRONT LH DOOR UPPER HINGE	BENT	32.40	32.40
1	FRONT LH DOOR LOWER HINGE	BENT	32.40	32.40
1	LH ROCKER PANEL	DENTED	2,373.70	2,373.70
1	LH PILLER B (BETWEEN FRT DOOR AND SLIDING DR)	DENTED	1,987.90	1,987.90
1	FRONT LH DOOR LOCK	NOT NECESSARY	48.99	-
1	FRONT LH DOOR SPEAKER JBL	NOT NECESSARY	230.00	-
1	FRONT LH DOOR VISOR	NOT NECESSARY	35.00	-
1	FRONT DOOR STEP	BENT	30.15	30.15
1	FRONT REST PANEL	NOT NECESSARY	40.24	-
12	FRONT DOOR CLIPS	NECESSARY	60.00	60.00
1	SLIDING DOOR LH	DENTED	695.91	695.91
			7,385.36	6,685.84
	<u>LABOUR</u>			
	REMOVE, INSTALL & RENEW :- FRONT LH FENDER, LH HEADLAMP, FENDER LINER, FRONT LH DOOR, LH ROCKER PANEL, FENDER GRILLS, WIND MIRROR, DOOR WINDOW PILLER B, LH SLIDING DOOR.		3,600.00	3,200.00
	PANEL BEATING FOR ROCKER PANEL INNER, PILLER B, LH SLIDING DOOR, AND LH QUOTER PANEL.		3,200.00	1,200.00

Report Ref No. CS/UOI22007814/Eqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COMPUTER WHEEL ALIGNMENT - ALL 4 WHEELS.	NOT NECESSARY	200.00	200.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.		800.00	-
	SECURE SERCURITY AREA FOR ELECTRIC VEHICLE UNPLUG OEM WITH RELEASE CURRENT.		1,800.00	1,200.00
	RESPRAY PREMIER & PAINT: FRONT LH FENDER, LH FRONT DOOR, LH SLIDING DOOR, ROCKER PANEL, B PILLER, CENTER PILLER, LH QUARTER PANEL AND SURFACE REAR BUMPER.		4,200.00	3,000.00
			13,800.00	8,800.00
GRAND TOTAL			21,185.36	15,485.84

RECOMMENDED COST OF REPAIRS			15,485.84
LESS EXCESS			-750.00
NETT LIABILITY			14,735.84

Report Ref No. CS/UOI22007814/Eqy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.