

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref	f:	CS3/INC22007815/Svy3m4	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Dat	te:	26/08/2022	
	ATTN: RODERIC Y	/UEN	Cod	de:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLA 732Z	Veh. Inspected		SMZ 988J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1184228-002	Excess (\$)		0.00	
	Assign From	DIANA TAY	Assign Date		16/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	BMW 316I	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WBA3A16030NS36620	Colour		SILVER	
	Odometer	91413 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/40 ZR18	TOURADOR		5 mm	
	L/H Front Tyre	235/40 ZR18	TOURADOR		5 mm	
	R/H Rear Tyre	235/40 ZR18	TOURADOR		6 mm	
	L/H Rear Tyre	235/40 ZR18	TOURADOR		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR N/S PORTION.				
5.	General Information					
	Accident Date	13/08/2022	Inspect Date / Time	е	16/08/2022 (10:30 AM)	
	Survey held at	8 KAKI BUKIT AVE 4, #02-24, PI	REMIER @ KAKI BUKI	IT		
	Repairer	D'S GRAFFITI CONCEPTS PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/INC22007815/Svy3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser