



kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/6412/4054/TP/06.22
Date : 14 July 2022

To: Arts East Plasterglassdesign
c/o Blk 5035, Ang Mo Kio Industrial Park 2
#01-353
Singapore 569538

VEHICLE APPRAISAL REPORT

Name of Workshop : Kwee Seng Motor Services
Place of inspection : Blk 5035, Ang Mo Kio Industrial Park 2, #01-353, Singapore 569538
Date of Assignment : 15 June 2022
Date of Accident : 13 June 2022
Date of Inspection : 15 June 2022

PARTICULARS OF INSPECTED VEHICLE

Registration No. : GX 4054J
Make / Model : Toyota Dyna 150D
Year of Manufacture/Reg : 2004
Colour : Silver
Class / Type : Lorry

Chassis Frame No. : JTFUF34Y803002344
Engine No. (Logcard) : 5L5426584
Odometer Reading : 450,080 KM

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Good
Paintwork : Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	FALKEN 185 R14C	7 mm
Front R	FALKEN 185 R14C	7 mm
Rear L	SUMITOMO 155 R12	7 mm
Rear R	SUMITOMO 155 R12	7 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	tailgate	buckled	\$ 1,641.00	\$ 1,641.00
2	2 pcs	tailgate hinges @\$35.00	bent	\$ 140.00	\$ 140.00
3	2 pcs	tailgate side hinge @\$142.00	bent	\$ 284.00	\$ 284.00
4	1 pc	tailgate "toyota" sticker	necessary	\$ 240.00	\$ 240.00
5	1 pc	l/h rear corner panel	buckled	\$ 179.00	\$ 179.00
6	1 pc	r/h rear corner panel	buckled	\$ 179.00	\$ 179.00
7	1 pc	l/h rear corner panel rubber stopper	missing	\$ 50.00	\$ 50.00
8	1 pc	r/h rear corner panel rubber stopper	missing	\$ 50.00	\$ 50.00
9	1 pc	rear floor panel	buckled	\$ 2,113.40	repair
10	1 pc	rear step panel	buckled	\$ 650.00	\$ 650.00
11	1 pc	l/h taillamp	cracked	\$ 272.00	\$ 272.00
12	1 pc	r/h taillamp	cracked	\$ 272.00	\$ 272.00
13	1 pc	l/h taillamp base panel	buckled	\$ 102.00	\$ 102.00
14	1 pc	r/h taillamp base panel	buckled	\$ 102.00	\$ 102.00
15	1 pc	front bumper	buckled	\$ 654.15	\$ 654.15
16	1 pc	front bumper reinforcement	buckled	\$ 174.20	\$ 174.20
17	1 pc	front grille	cracked	\$ 653.10	\$ 653.10
18	1 pc	front logo emblem	necessary	\$ 154.35	\$ 154.35
19	1 pc	front panel	damaged	\$ 1,144.10	repair
20	1 pc	l/h headlamp	cracked	\$ 699.45	\$ 699.45
21	1 pc	fuel tank level float	buckled	\$ 365.20	\$ 365.20
Less 25%				\$ 10,118.95	\$ 6,861.45
					\$ 1,715.36
SPECIAL NETT ITEMS:-				\$ 10,118.95	\$ 5,146.09
22	1 pc	tailgate "70k/h" sticker	necessary	\$ 30.00	\$ 25.00
23	1 pc	tailgate "13 pax" sticker	necessary	\$ 30.00	\$ 25.00
24	1 pc	front no. plate	buckled	\$ 60.00	\$ 50.00
				\$ 120.00	\$ 100.00
Sub - Total				\$ 10,238.95	\$ 5,246.09

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 10,238.95	\$ 5,246.09
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,600.00	\$ 1,400.00
2		To realign headlamp focus		\$ 35.00	\$ 20.00
3		To check all wiring and rewire		\$ 120.00	\$ 100.00
4		To remove and reinstall tailgate components		\$ 80.00	\$ <i>nn</i> 60.00
5		To remove and reinstall fuel tank		\$ 160.00	\$ <i>nn</i> 120.00
6		To apply anti-rust		\$ 80.00	\$ 60.00
7		To putty and spray-paint of affected areas		\$ 1,400.00	\$ 1,200.00
				\$ 3,475.00	\$ 2,960.00
Sub - Total				\$ 13,713.95	\$ 8,206.09

1000/

400

X

1000/

7 days