KWEE SENG MOTOR SERVICES

BLK 5035, ANG MO KIO INDUSTRIAL PARK 2 #01-353 SINGAPORE 569538 H/P 9147 8165

22 July 2022

ARTS EAST PLASTER GLASS DESIGN c/o Blk 5035 Ang Mo Kio Industrial Park 2 #01-353 Singapore 569538

FINAL REPAIR COSTS VEHICLE NO. GX 4504 J

Repair costs for vehicle no. **GX 4054 J** as per Kelvin Automotive Appraising Services Report dated 14 July 2022 (Lump Sum) **\$\$6,850.00**

SINGAPORE DOLLARS: SIX THOUSAND EIGHT HUNDRED & FIFTY ONLY



tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Claim Reference Insured Vehicle No. Thirty Party Veh No. Officer-In-Charge

Our Reference

: KAAS/TA/6412/4054/TP/06.22

Invoice No.

: 6412

Date

14 July 2022

To: Arts East Plasterglassdesign

c/o Blk 5035, Ang Mo Kio Industrial Park 2

#01-353

Singapore 569538

<u>INVOICE</u>					
PARTICULARS		AMOUNT			
Vehicle No. : GX 4054J Make/Model : Toyota Dyna 150D					
✓ Inspection of Vehicle					
✓ Appraisal Report					
✓ 52 Colored Photographs		SGD 647.00			
✓ Transport charges					
✓ Re-inspection		ω			
Others (Specify)					
	Total	SGD 647.00			

Dollars: Six Hundred and Forty-Seven Only

(Cheque should be crossed and make payable to " Kelvin Automotive Appraising Services ")



Kelvin Automotive Appraising Services



tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference

: KAAS/TA/6412/4054/TP/06.22

Date

: 14 July 2022

To: Arts East Plasterglassdesign

c/o Blk 5035, Ang Mo Kio Industrial Park 2

#01-353

Singapore 569538

VEHICLE APPRAISAL REPORT

Name of Workshop

: Kwee Seng Motor Services

Place of inspection

: Blk 5035, Ang Mo Kio Industrial Park 2, #01-353, Singapore 569538

Date of Assignment

: 15 June 2022

Date of Accident

Date of Inspection

13 June 202215 June 2022

PARTICULARS OF INSPECTED VEHICLE

Registration No.

: GX 4054J

Chassis Frame No.

Odometer Reading

: JTFUF34Y803002344

Make / Model

: Toyota

Dyna 150D Engine No. (Logcard)

: 5L5426584 : 450,080 KM

Year of Manufacture/Reg

: 2004

vianulaciule/11eg ...2

: Silver

Colour Class / Type

: Lorry

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition

: Good

Paintwork

: Good

Market Value

: -

Scrap Value

: -

CONDITION OF TYRES ON VEHICLE

		Make/Size	Thread Balance
Front	L	FALKEN 185 R14C	7 mm
Front	R	FALKEN 185 R14C	7 mm
Rear	L	SUMITOMO 155 R12	7 mm
Rear	R	SUMITOMO 155 R12	7 mm

^{*}The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Our Reference

: KAAS/TA/6412/4054/TP/06.22

Vehicle Number : GX 4054J

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate		Revised Amount	
		LIST ITEMS:-		\top			
1	1 pc	tailgate	buckled	\$	1,641.00	\$	1,641.00
2	4 pcs	tailgate hinges @S\$35.00	bent	\$	140.00	\$	140.00
3	2 pcs	tailgate side hinge @S\$142.00	bent	\$	284.00	\$	284.00
4	1 pc	tailgate " toyota " sticker	necessary	\$	240.00	\$	240.00
5	1 pc	I/h rear corner panel	buckled	\$	179.00	\$	179.00
6	1 pc	r/h rear corner panel	buckled	\$	179.00	\$	179.00
7	1 pc	I/h rear corner panel rubber stopper	missing	\$	50.00	\$	50.00
8	1 pc	r/h rear corner panel rubber stopper	missing	\$	50.00	\$	50.00
9	1 pc	rear floor panel	buckled	\$	2,113.40	100	repair
10	1 pc	rear step panel	buckled	\$	650.00	\$	650.00
11	1 pc	I/h taillamp	cracked	\$	272.00	\$	272.00
12	1 pc	r/h taillamp	cracked	\$	272.00	\$	272.00
13	1 pc	I/h taillamp base panel	buckled	\$	102.00	\$	102.00
14	1 pc	r/h taillamp base panel	buckled	\$	102.00	\$	102.00
15	1 pc	front bumper	buckled	\$	654.15	\$	654.15
16	1 pc	front bumper reinforcement	buckled	\$	174.20	\$	174.20
17	1 pc	front grille	cracked	\$	653.10	\$	653.10
18	1 pc	front logo emblem	necessary	\$	154.35	\$	154.35
19	1 pc	front panel	damaged	\$	1,144.10		repair
20	1 pc	I/h headlamp	cracked	\$	699.45	\$	699.45
21	1 pc	fuel tank level float	buckled	\$	365.20	\$	365.20
		2		\$	10,118.95	\$	6,861.45
		Less 25%		_		\$	1,715.36
		<		\$	10,118.95	\$	5,146.09
		SPECIAL NETT ITEMS:-	~				
				١.			
22	1 pc	tailgate " 70k/h " sticker	necessary	\$	30.00	\$	25.00
23	1 pc	tailgate " 13 pax " sticker	necessary	\$	30.00	\$	25.00
24	1 pc	front no. plate	buckled	\$	60.00	\$	50.00
		19C		\$	120.00	\$	100.00
		Made Made					
1			Sub - Total	\$	10,238.95	\$	5,246.09



6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Our Reference Vehicle Number : KAAS/TA/6412/4054/TP/06.22

: GX 4054J

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	8,7 4	Revised Amount
П		BIF		\$ 10,238.95	\$	5,246.09
		LABOUR & OTHER CHARGES:-				
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,600.00	\$	1,400.00
2		To realign headlamp focus		\$ 35.00	\$	20.00
3		To check all wiring and rewire		\$ 120.00	\$	100.00
4		To remove and reinstall tailgate components		\$ 80.00	\$	60.00
5		To remove and reinstall fuel tank		\$ 160.00	\$	120.00
6		To apply anti-rust	-	\$ 80.00	\$	60.00
7		To putty and spray-paint of affected areas		\$ 1,400.00	\$	1,200.00
				\$ 3,475.00	\$	2,960.00
		3				
			Sub - Total	\$ 13,713.95	\$	8,206.0



tel: 6746 2118 fax: 6746 1148

reg no: 53058468m


Our Reference Vehicle Number KAAS/TA/6412/4054/TP/06.22

: GX 4054J

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered Squarely to the Rear portion of the vehicle.







The general area of damages is at the

Rear portion

(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs

Kwee Seng Motor Services

\$ 13,713.95 .

We have adjusted the cost to

8,206.09 and the repairer has agreed to undertake the repairs at a

Contract Lump Sum of

\$ 6,850.00 to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of

\$

7 working days.

52 photographs were taken at the time of static inspection.

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. we thank you for engaging our services.

6412

for our services rendered and

KELVIN AUTOMOTIVE APPRAISING SERVICES



KELVIN TEO

Licensed Automotive Appraiser Nitec in Automotive Technology Cert. Crash Investigation & Reconstruction Dip MS

MSAAA, AM SAE-A

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.









