

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007821/UNY3Q2**Date:** 25/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00060732204

Claimant Vehicle No : GBL5261T **Insured Vehicle No :** GBH4567P

Date of Loss: 15/08/2022 Nature of Claim: TP Claim No: SNM22D205688/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL5261T**

Make & Model: NISSAN NV200, 1.6 PETROL (A) Engine No: HR16184013D

Reg. Date: 30/09/2021 (Man. Year: 2021) Chassis No: JN1YAAM20Z0001753

Colour: White Odometer: 21989 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/80 R14 Rear Tyre Size: 165/80 R14

Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm

Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,992.00	6,187.13	11,804.87	65.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,170.00	1,730.00	44.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,892.00	8,357.13	13,534.87	61.83
Approved Total (Overridden) (\$\$)		6,600.00		
Nett Amount (\$\$)	21,892.00	6,600.00	15,292.00	69.85

INSPECTION

Date of Assignment: 16/08/2022

Date Inspected: 17/08/2022 Inspected At: Nineteen Autowerks Pte Ltd - Woodlands (HQ)
39 Woodlands Close, MEGA@Woodlands #01-24
Singapore 737856

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Aug 2022)	
Parts:	N/A	NISSAN NV200 1.6 PETROL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5261T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	788.00 F	*534.50 FL
2	2		*REAR BUMPER REFLECTOR	Necessary	110.00 F	*50.00 FL
3	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	242.00 F	*45.50 FL
4	1		*REAR BUMPER SPONGE	Torn	121.00 F	*121.00 FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	49.50 F	*- FL
6	1		*TAIL LAMP	N/S Cracked /O/S Not Necessary	916.00 F	*335.40 FL
7	2		*TAIL LAMP PANEL	Repair	952.00 F	*- FL
8	2		*TAIL LAMP INNER PANEL	Repair	1,378.00 F	*- FL
9	1		*TAILGATE	Badly Dented	1,873.24 F	*1,873.24 FL
10	1		*TAILGATE EMBLEM -NV200	Necessary	144.48 F	*82.50 FL
11	1		*TAILGATE LOGO	Necessary	94.81 F	*80.00 FL
12	1		*REAR FENDER LH	Repair	1,791.60 F	*- FL
13	1		*REAR FENDER INNER PANEL LH	Repair	667.40 F	*- FL
14	1		*TAILGATE WEATHERSTRIP (INNER)	Twisted	325.00 F	*132.80 FL
15	1		*TAILGATE WIPER MOTOR	Bent / Jammed	689.00 F	*540.50 FL
16	1		*TAILGATE WIPER ARM	Bent	51.00 F	*51.00 FL
17	1		*REAR END PANEL (INNER)	Badly Dented	718.00 F	*718.00 FL
18	1		*REAR END PANEL	Badly Dented	354.00 F	*248.20 FL
19	1		*REAR END PANEL TOP GARNISH	Cracked	124.00 F	*124.00 FL
20	1		*REAR FLOOR PANEL	Repair	1,895.00 F	*- FL
21	1		*REAR FLOOR PANEL TOP MAT	Not Necessary	653.40 F	*- FL
22	1		*REAR EXTENSION MEMBER	Bent	854.00 F	*241.00 FL
23	1		*REAR SPARE TYRE BRACKETS	Not Necessary	561.00 F	*- FL
24	1		*REAR SIDE PANEL AIR VENT INNER	Not Necessary	78.00 F	*- FL
25	1		*REAR SPARE TYRE LOCK WITH BOLT	Not Necessary	59.07 F	*- FL
26	1		*TAILGATE INNER LOCK	Dented / Shorted	148.80 F	*148.80 FL
27	1		*TAILGATE INNER TRIM	Distorted / Torn	241.20 F	*241.20 FL
28	1		*TAILGATE OUTER GARNISH	Grazed	262.50 F	*262.50 FL
29	1		*REAR END DOOR 70KM/H STICKER LH	Necessary	50.00 FS	*10.00 FS
30	1		*REAR DOOR WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*40.00 FS
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
32	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*REAR TAILLAMP CLIPS SET LH	Not Necessary	40.00 FS	*- FS
34	1		*REAR PANEL SEALANT	Necessary	20.00 FS	*20.00 FS
35	1		*REAR FENDER SEALANT LH	Not Necessary	60.00 FS	*- FS
36	1		*COMPANY STICKER ADVERTISEMENT	Necessary	1,200.00 FS	*600.00 FS
37	1		*REAR LICENCE PLATE	Bent	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,992.00 6,770.14
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 583.01

Total Parts (\$\$) 17,992.00 6,187.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,800.00	1,100.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,500.00	800.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	80.00	80.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	20.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
6	TO DISMANTLE & REINSTALL REAR WINDSCREEN	New	280.00	120.00
7	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$\$)			3,900.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >